

Carroll Co Career Tech Ctr

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047041-01	Cosmetology Fountain	11/17/2016	07:29	7.5	0.131	3.9	PASS
E047041-02	Auditorium Fountain	11/17/2016	07:31	7.5	0.066	<1.0	PASS
E047041-03	Kitchen Serving Line Hand Sink	11/17/2016	07:32	7.6	0.043	1.2	PASS
E047041-04	Kitchen Double Sink	11/17/2016	07:33	7.6	0.037	1.0	PASS
E047041-05	Kitchen Single Sink	11/17/2016	07:33	7.6	0.059	5.7	PASS
E047041-06	Fountain Kitchen	11/17/2016	07:33	7.4	0.071	<1.0	PASS
E047041-07	Kitchen Center Hand Sink	11/17/2016	07:34	7.5	0.037	<1.0	PASS
E047041-08	Kitchen Sink by Ice Machine	11/17/2016	07:34	7.5	0.051	1.8	PASS
E047041-09	Kitchen Hand Sink by Stoves	11/17/2016	07:34	7.5	0.090	3.6	PASS
E047041-10	Hand Sink Dishwashing Room	11/17/2016	07:34	7.5	0.030	1.7	PASS
E047041-11	Hand Sink Pots Room	11/17/2016	07:35	7.5	0.093	<1.0	PASS
E047041-12	Pots Room Triple Sink Right	11/17/2016	07:38	7.5	0.032	2.1	PASS
E047041-13	Pots Room Triple Sink Left	11/17/2016	07:38	7.5	0.090	2.1	PASS
E047041-14	Fountain B112	11/17/2016	07:39	7.5	0.189	<1.0	PASS
E047041-15	Fountain B122	11/17/2016	07:36	7.5	0.073	1.3	PASS
E047041-16	Fountain B127	11/17/2016	07:37	7.5	0.076	<1.0	PASS
E047041-17	Fountain B118	11/17/2016	07:54	7.5	0.104	1.7	PASS
E047041-18	Fountain B121	11/17/2016	07:54	7.6	0.164	<1.0	PASS
E047041-19	Masonry Room Fountain	11/17/2016	07:55	7.6	0.126	1.7	PASS
E047041-20	Fountain B134	11/17/2016	07:57	7.6	0.059	<1.0	PASS
E047041-21	Fountain B135	11/17/2016	07:58	7.6	0.147	7.4	PASS
E047041-22	Electrical Construction Fountain	11/17/2016	07:59	7.5	0.064	1.0	PASS
E047041-23	Loading Dock Fountain	11/17/2016	08:00	7.5	0.106	<1.0	PASS
E047041-24	Fountain Services Team	11/17/2016	08:00	7.6	0.099	3.0	PASS
E047041-25	Fountain Physical Rehab	11/17/2016	08:00	7.6	0.087	1.8	PASS
E047041-26	Cosmetology	11/17/2016	08:01	7.6	0.088	1.2	PASS
E047041-27	Fountain Print Production	11/17/2016	08:03	7.5	0.117	2.2	PASS
E047041-28	Lower Hallway Fountain	11/17/2016	08:04	7.5	0.093	<1.0	PASS

Carroll Co Career Tech Ctr

E047041-29	Fountain A6	11/17/2016	08:05	7.4	0.063	2.6	PASS
E047041-30	Fountain Collision Repair Right	11/17/2016	08:06	7.4	0.149	<1.0	PASS
E047041-31	Fountain Collision Repair Left	11/17/2016	08:06	7.5	0.094	1.2	PASS
E047041-32	Fountain BioMedical Science	11/17/2016	08:08	7.5	0.104	1.7	PASS
E047041-33	Fountain HVAC	11/17/2016	08:12	7.5	0.208	<1.0	PASS
E047041-34	Fountain Welding Lab	11/17/2016	08:13	7.5	0.130	<1.0	PASS

Carroll Springs

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047196-01	Kitchen Hand Sink by Entrance	12/02/2016	07:10	7.2	0.732	62.6	FAIL
E047196-02	Kitchen Double Sink by Entrance	12/02/2016	07:11	7.1	0.800	37.8	FAIL
E047196-03	Dishroom Hand Sink	12/02/2016	07:11	7.1	0.524	56.5	FAIL
E047196-04	Dishroom Triple Slnk Right	12/02/2016	07:11	7.0	0.364	86.5	FAIL
E047196-05	Fountain Rm 34	12/02/2016	07:12	7.0	1.32	21.6	FAIL
E047196-06	Fountain Outside Rm 48	12/02/2016	07:13	7.0	0.322	23.8	FAIL
E047196-07	Fountain Between Rm 6 & 7	12/02/2016	07:14	7.0	1.18	15.2	PASS
E047196-08	Fountain Between Rm 16 & 17	12/02/2016	07:15	6.9	1.40	13.9	FAIL
E047196-09	Faculty Lounge Sink	12/02/2016	07:17	7.0	0.270	8.0	PASS
E047196-10	Rm 119	12/02/2016	07:19	6.9	0.523	18.2	PASS

Carrolltowne ES

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047183-01	Kitchen Single Sink Right of Refrigerators	12/01/2016	06:17	7.1	0.416	283	FAIL
E047183-02	Kitchen Hand Slnk	12/01/2016	06:17	7.1	0.212	56.9	FAIL
E047183-03	Kitchen Triple Sink Right	12/01/2016	06:18	8.3	0.170	10.8	PASS
E047183-04	Kitchen Triple Sink Left	12/01/2016	06:18	8.3	0.154	74.1	FAIL
E047183-05	Kitchen Double Sink	12/01/2016	06:18	8.3	0.104	1.4	PASS
E047183-06	Kitchen Single Sink Left of Refrigerators	12/01/2016	06:18	6.8	10.2	561	FAIL
E047183-07	Kitchen Pot Filler	12/01/2016	06:21	6.9	0.115	5.2	PASS
E047183-08	Kitchen Water Fountain	12/01/2016	06:22	7.8	4.84	26.2	FAIL
E047183-09	Kitchen Hand Sink Behind Food Line	12/01/2016	06:23	7.8	0.158	5.3	PASS
E047183-10	Fountain Outside Rm 188	12/01/2016	06:24	8.2	0.071	<1.0	PASS
E047183-11	Room 116A Bubblers	12/01/2016	06:26	8.2	0.108	<1.0	PASS
E047183-12	Room 116B Bubblers	12/01/2016	06:27	8.2	0.125	<1.0	PASS
E047183-13	Room 116C Bubblers	12/01/2016	06:27	8.3	0.109	<1.0	PASS
E047183-14	Room 116D Bubblers	12/01/2016	06:28	8.3	0.110	<1.0	PASS
E047183-15	Hall Fountain by Media Ctr	12/01/2016	06:29	8.3	0.163	2.2	PASS
E047183-16	Room 117A Bubblers	12/01/2016	06:30	8.4	0.103	<1.0	PASS
E047183-17	Room 117B Bubblers	12/01/2016	06:30	8.4	0.119	<1.0	PASS
E047183-18	Room 117C Bubblers	12/01/2016	06:30	8.4	0.118	<1.0	PASS
E047183-19	Room 117D Bubblers	12/01/2016	06:30	8.4	0.126	<1.0	PASS
E047183-20	Room 143 Bubblers	12/01/2016	06:32	8.4	0.125	<1.0	PASS
E047183-21	Room 140C Bubblers	12/01/2016	06:33	8.4	0.126	<1.0	PASS
E047183-22	Room 140B Bubblers	12/01/2016	06:33	8.5	0.146	<1.0	PASS
E047183-23	Room 140A Bubblers	12/01/2016	06:34	8.5	0.128	<1.0	PASS
E047183-24	Room 134 Bubblers	12/01/2016	06:35	8.5	0.105	<1.0	PASS
E047183-25	Room 136 Bubblers	12/01/2016	06:35	8.5	0.106	<1.0	PASS
E047183-26	Room 137 Buubler	12/01/2016	06:35	8.5	0.101	<1.0	PASS
E047183-27	Room 138 Bubblers	12/01/2016	06:35	8.5	0.106	<1.0	PASS
E047183-28	Fountain by Room 142	12/01/2016	06:39	8.5	0.084	<1.0	PASS
E047183-29	Room 133A Bubblers	12/01/2016	06:40	8.2	0.116	<1.0	PASS
E047183-30	Room 133B Bubblers	12/01/2016	06:40	8.6	0.123	<1.0	PASS

Carrolltowne ES

E047183-31	Room 133C Bubbler	12/01/2016	06:40	8.6	0.123	<1.0	PASS
E047183-32	Room 133D Bubbler	12/01/2016	06:40	8.6	0.117	<1.0	PASS
E047183-33	Room 123A Bubbler	12/01/2016	06:42	8.6	0.126	<1.0	PASS
E047183-34	Room 123B Bubbler	12/01/2016	06:42	8.6	0.127	<1.0	PASS
E047183-35	Room 123C Bubbler	12/01/2016	06:42	8.6	0.127	<1.0	PASS
E047183-36	Room 123D Bubbler	12/01/2016	06:42	8.6	0.131	<1.0	PASS
E047183-37	Room 161A Bubbler	12/01/2016	06:44	8.7	0.168	16.7	PASS
E047183-38	1st Grade Extension Bubbler	12/01/2016	06:45	8.7	0.115	5.2	PASS
E047183-39	Naylor Bubbler	12/01/2016	06:45	8.7	0.304	4.1	PASS
E047183-40	E1K Fountain	12/01/2016	06:47	8.8	0.143	7.9	PASS
E047183-41	Room 231 Bubbler	12/01/2016	06:48	8.8	0.142	1.5	PASS
E047183-42	Room 161 Bubbler	12/01/2016	06:50	8.8	0.693	3.8	PASS
E047183-43	Room 152 Bubbler	12/01/2016	06:51	8.5	0.465	14.5	PASS
E047183-44	Fountain by Gym Office	12/01/2016	06:54	8.6	0.081	<1.0	PASS

Century HS

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047145-01	Kitchen Hand Sink by Serving Line	11/29/2016	06:04	6.8	0.198	2.6	PASS
E047145-02	Kitchen Triple Sink	11/29/2016	06:04	6.8	0.101	2.4	PASS
E047145-03	Kitchen Pot Filler	11/29/2016	06:05	7.8	0.029	<1.0	PASS
E047145-04	Dishroom Triple Sink Right	11/29/2016	06:06	7.8	0.105	1.0	PASS
E047145-05	Dishroom Triple Sink Left	11/29/2016	06:06	7.6	0.045	5.5	PASS
E047145-06	Dishroom Hand Sink	11/29/2016	06:07	7.6	0.142	5.9	PASS
E047145-07	D113 Faculty Dining Sink	11/29/2016	06:08	7.6	0.164	<1.0	PASS
E047145-08	Fountain Outside Cafeteria Right	11/29/2016	06:09	7.6	0.130	<1.0	PASS
E047145-09	Fountain Outside Cafeteria Center	11/29/2016	06:09	7.8	0.210	<1.0	PASS
E047145-10	Fountain Outside Cafeteria Left	11/29/2016	06:09	7.8	0.161	<1.0	PASS
E047145-11	C110 Sink	11/29/2016	06:11	7.8	0.164	<1.0	PASS
E047145-12	Fountain Main Office Right	11/29/2016	06:12	7.8	0.191	<1.0	PASS
E047145-13	Fountain Main Office Left	11/29/2016	06:12	7.8	0.302	<1.0	PASS
E047145-14	Fountain Guidance Office Right	11/29/2016	06:13	7.8	0.895	4.8	PASS
E047145-15	Fountain Guidance Office Left	11/29/2016	06:13	7.8	1.81	18.2	FAIL
E047145-16	Fountain A100 Wing Right	11/29/2016	06:15	7.8	0.264	<1.0	PASS
E047145-17	Fountain A100 Wing Left	11/29/2016	06:15	7.8	0.172	<1.0	PASS
E047145-18	Fountain B100 Wing Right	11/29/2016	06:16	7.9	0.177	<1.0	PASS
E047145-19	Fountain B100 Wing Left	11/29/2016	06:16	7.9	0.257	<1.0	PASS
E047145-20	Fountain B200 Wing Right	11/29/2016	06:18	7.9	0.181	<1.0	PASS
E047145-21	Fountain B200 Wing Left	11/29/2016	06:18	7.9	0.163	<1.0	PASS
E047145-22	Sink Room B215 Station 1	11/29/2016	06:20	7.9	0.139	2.1	PASS
E047145-23	Sink Room B215 Station 2	11/29/2016	06:20	7.8	0.116	1.6	PASS
E047145-24	Sink Room B215 Station 3	11/29/2016	06:20	7.8	0.131	3.5	PASS
E047145-25	Sink Room B215 Station 4	11/29/2016	06:20	7.9	0.112	1.9	PASS
E047145-26	Sink Room B215 Station 5	11/29/2016	06:20	7.8	0.156	<1.0	PASS

Century HS

E047145-27	Sink Room B215 Startion 6	11/29/2016	06:20	7.8	0.156	<1.0	PASS
E047145-28	Sink Room B215 Startion 7	11/29/2016	06:20	7.8	0.113	<1.0	PASS
E047145-29	Sink Room B215 Teachers Station	11/29/2016	06:20	7.8	0.187	<1.0	PASS
E047145-30	Fountain A200 Wing Right	11/29/2016	06:26	7.8	0.193	<1.0	PASS
E047145-31	Fountain A200 Wing Left	11/29/2016	06:26	7.9	0.162	<1.0	PASS

Cranberry Station ES

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047197-01	Kitchen Hand Sink by Double Sink	12/02/2016	07:37	7.2	0.146	14.7	PASS
E047197-02	Kitchen Double Sink	12/02/2016	07:37	7.3	0.075	1.9	PASS
E047197-03	Dishroom Triple Sink Right	12/02/2016	07:38	7.3	0.295	118	FAIL
E047197-04	Dishroom Triple Sink Left	12/02/2016	07:38	7.3	0.095	8.9	PASS
E047197-05	Kitchen Pot Filler	12/02/2016	07:39	7.1	0.684	179	FAIL
E047197-06	Kitchen Hand Sink by Back Door	12/02/2016	07:40	7.1	0.368	8.3	PASS
E047197-07	Fountain Between 215 & 216 Right	12/02/2016	07:45	7.2	0.267	<1.0	PASS
E047197-08	Fountain Between 215 & 216 Left	12/02/2016	07:45	7.3	0.528	<1.0	PASS
E047197-09	Fountain by Rm 419	12/02/2016	07:46	7.4	0.424	<1.0	PASS
E047197-10	Fountain Between 406 & 407 Right	12/02/2016	07:47	7.4	0.327	<1.0	PASS
E047197-11	Fountain Between 406 & 407 Left	12/02/2016	07:47	7.4	0.244	<1.0	PASS
E047197-12	Fountain Between 309 & 310 Right	12/02/2016	07:50	7.5	0.221	<1.0	PASS
E047197-13	Fountain Between 309 & 310 Left	12/02/2016	07:50	7.5	0.480	<1.0	PASS
E047197-14	Sink Health Suite	12/02/2016	07:52	7.5	0.165	9.2	PASS
E047197-15	Sink Rm 103	12/02/2016	07:52	7.6	0.329	2.8	PASS
E047197-16	Fountain Between 120 & 121	12/02/2016	07:54	7.6	0.228	<1.0	PASS
E047197-17	Faculty Rm 125 Sink	12/02/2016	07:55	7.6	0.200	<1.0	PASS

East Middle

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047246-01	Sink Behind Serving Line	12/06/2016	05:55	6.5	0.174	7.8	PASS
E047246-02	Kitchen Hand Sink by Entrance	12/06/2016	05:56	6.5	0.239	22.5	FAIL
E047246-03	Kitchen Double Sink b Ice Machine	12/06/2016	05:57	6.6	0.157	34.4	FAIL
E047246-04	Kitchen Triple Sink Right	12/06/2016	05:58	6.6	0.257	26.1	FAIL
E047246-05	Kitchen Triple Sink Left	12/06/2016	05:58	6.6	0.271	19.5	PASS
E047246-06	Cafeteria Fountain	12/06/2016	06:00	6.7	0.155	3.7	PASS
E047246-07	Dishroom Hand Sink	12/06/2016	06:01	6.7	0.259	40.1	FAIL
E047246-08	Fountain by A012 Right	12/06/2016	06:02	6.8	0.084	1.3	PASS
E047246-09	Fountain by A012 Left	12/06/2016	06:02	6.9	0.107	<1.0	PASS
E047246-10	Fountain by C101/C102	12/06/2016	06:03	6.9	0.058	2.6	PASS
E047246-11	Fountain by A034 Right	12/06/2016	06:07	7.0	0.064	<1.0	PASS
E047246-12	Fountain by A034 Left	12/06/2016	06:07	7.0	0.104	1.5	PASS
E047246-13	Room C110 Sink Station 1	12/06/2016	06:10	7.0	0.196	5.5	PASS
E047246-14	Room C110 Sink Station 2	12/06/2016	06:10	7.0	0.210	14.1	PASS
E047246-15	Room C110 Sink Station 3	12/06/2016	06:10	7.0	0.295	19.4	PASS
E047246-16	Room C110 Sink Station 4	12/06/2016	06:10	7.0	0.249	19.1	PASS
E047246-17	Room C110 Sink Station 5	12/06/2016	06:10	7.1	0.303	36.4	FAIL
E047246-18	Room C110 Sink Teachers	12/06/2016	06:12	7.1	0.098	28.2	FAIL
E047246-19	Fountain Portable B	12/06/2016	06:19	7.1	0.694	<1.0	PASS
E047246-20	Gym Fountain	12/06/2016	06:21	7.2	0.086	<1.0	PASS
E047246-21	Fountain byC012	12/06/2016	06:22	7.2	0.242	<1.0	PASS
E047246-22	Fountain by A107 Right	12/06/2016	06:24	7.3	0.110	<1.0	PASS
E047246-23	Fountain by A107 Left	12/06/2016	06:24	7.3	0.090	1.3	PASS
E047246-24	Fountain by A228 Right	12/06/2016	06:26	7.3	0.111	2.4	PASS
E047246-25	Fountain by A228 Left	12/06/2016	06:26	7.3	0.245	1.1	PASS
E047246-26	Fountain by A206 Right	12/06/2016	06:28	7.3	0.074	1.4	PASS
E047246-27	Fountain by A206 Left	12/06/2016	06:28	7.3	0.108	2.1	PASS
E047246-28	Sink in A232	12/06/2016	06:30	7.4	0.137	4.1	PASS
E047246-29	Sink Main Office	12/06/2016	06:32	7.4	0.134	3.7	PASS

Ebb Valley ES

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047084-01	Kitchen Double Sink	11/22/2016	06:00	7.1	0.407	7.2	PASS
E047084-02	Kitchen Rear Hand Sink	11/22/2016	06:02	7.2	0.191	6.7	PASS
E047084-03	Kitchen Middle Hand Sink	11/22/2016	06:03	7.2	0.349	13.2	PASS
E047084-04	Kitchen Triple Sink Left	11/22/2016	06:04	7.2	0.492	18.6	PASS
E047084-05	Kitchen Triple Sink Right	11/22/2016	06:05	7.2	0.071	29.0	FAIL
E047084-06	Dishroom Hand Sink	11/22/2016	06:06	7.2	0.455	4.3	PASS
E047084-07	Kitchen Front Hand Sink	11/22/2016	06:09	7.2	0.483	3.9	PASS
E047084-08	Dishroom Spray	11/22/2016	06:10	7.2	0.887	1.3	PASS
E047084-09	Kitchen Bathroom Sink	11/22/2016	06:11	7.3	0.424	8.4	PASS
E047084-10	Kitchen Serving Line	11/22/2016	06:12	7.3	0.530	2.0	PASS
E047084-11	Kitchen Pot Filler	11/22/2016	06:14	7.2	0.465	1.8	PASS
E047084-12	Custodian Hand Wash Sink	11/22/2016	06:16	7.3	0.379	6.0	PASS
E047084-13	Fountain A-130 Left	11/22/2016	06:18	7.3	0.397	<1.0	PASS
E047084-14	Fountain A-130 Right	11/22/2016	06:19	7.3	0.444	<1.0	PASS
E047084-15	Sink Rm A-130	11/22/2016	06:20	7.2	0.491	1.6	PASS
E047084-16	Bubbler Rm A-101	11/22/2016	06:22	7.5	0.386	<1.0	PASS
E047084-17	Sink Rm A-110	11/22/2016	06:23	7.5	0.544	9.9	PASS
E047084-18	Bubbler Rm A-122	11/22/2016	06:25	7.5	0.109	3.0	PASS
E047084-19	Bubbler Rm A-115	11/22/2016	06:26	7.4	0.138	1.6	PASS
E047084-20	Bubbler Rm A-117	11/22/2016	06:27	7.4	0.369	<1.0	PASS
E047084-21	Bubbler Rm B-118	11/22/2016	06:28	7.4	0.216	5.4	PASS
E047084-22	Bubbler Rm B-100	11/22/2016	06:30	7.4	0.091	1.1	PASS
E047084-23	Bubbler Rm B-117	11/22/2016	06:32	7.4	0.430	<1.0	PASS
E047084-24	Bubbler Rm B-102	11/22/2016	06:33	7.4	0.116	<1.0	PASS
E047084-25	Bubbler Rm B-103	11/22/2016	06:34	7.4	0.108	5.4	PASS
E047084-26	Bubbler Rm B-106	11/22/2016	06:36	7.7	0.049	3.3	PASS
E047084-27	Bubbler Rm B-107	11/22/2016	06:36	7.6	0.351	<1.0	PASS
E047084-28	Bubbler Rm B-119	11/22/2016	06:37	7.6	0.440	<1.0	PASS
E047084-29	Bubbler Rm B-120	11/22/2016	06:38	7.5	0.567	2.3	PASS
E047084-30	Bubbler Rm B-124	11/22/2016	06:43	7.5	0.412	2.0	PASS
E047084-31	Bubbler Rm B-155	11/22/2016	06:45	7.5	0.422	2.0	PASS
E047084-32	Bubbler Rm B-155 Bathroom	11/22/2016	06:45	7.4	0.736	2.6	PASS

Ebb Valley ES

E047084-33	Bubbler Rm B-129 Kitchen	11/22/2016	06:47	7.4	0.266	<1.0	PASS
E047084-34	Bubbler Rm B-150	11/22/2016	06:50	7.4	0.386	<1.0	PASS
E047084-35	Bubbler Rm B-148	11/22/2016	06:51	7.4	0.517	<1.0	PASS
E047084-36	Bubbler Rm B-133	11/22/2016	06:52	7.4	0.311	<1.0	PASS
E047084-37	Bubbler Rm B-134	11/22/2016	06:53	7.4	0.024	<1.0	PASS
E047084-38	Bubbler Rm B-142	11/22/2016	06:54	7.4	0.378	1.5	PASS
E047084-39	Bubbler Rm B-141	11/22/2016	06:55	7.4	0.388	<1.0	PASS
E047084-40	Bubbler Rm B-136	11/22/2016	06:56	7.5	0.222	1.3	PASS
E047084-41	Bubbler Rm B-231	11/22/2016	07:02	7.4	0.465	4.9	PASS
E047084-42	Bubbler Rm B-223	11/22/2016	07:05	7.4	0.555	<1.0	PASS
E047084-43	Bubbler Rm B-222	11/22/2016	07:06	7.4	0.470	2.7	PASS
E047084-44	Bubbler Rm B-213	11/22/2016	07:07	7.4	0.507	1.7	PASS
E047084-45	Bubbler Rm B-212	11/22/2016	07:08	7.4	0.683	2.7	PASS
E047084-46	Bubbler Rm B-221	11/22/2016	07:09	7.4	0.431	2.8	PASS
E047084-47	Bubbler Rm B-220	11/22/2016	07:10	7.4	0.484	3.4	PASS
E047084-48	Bubbler Rm B-210	11/22/2016	07:11	7.4	0.825	2.1	PASS
E047084-49	Bubbler Rm B-211	11/22/2016	07:12	7.4	0.725	1.6	PASS
E047084-50	Fountain by Rm 205 Left	11/22/2016	07:14	7.4	0.586	1.0	PASS
E047084-51	Fountain by Rm 205 Right	11/22/2016	07:14	7.4	0.619	1.2	PASS
E047084-52	Fountain by Rm 201 Left	11/22/2016	07:16	7.4	0.604	<1.0	PASS
E047084-53	Fountain by Rm 201 Right	11/22/2016	07:16	7.4	0.577	<1.0	PASS
E047084-54	Bubbler Rm B-203	11/22/2016	07:17	7.4	0.206	1.0	PASS
E047084-55	Bubbler Rm B-223	11/22/2016	07:18	7.4	0.497	1.5	PASS
E047084-56	Bubbler Rm B-222	11/22/2016	07:18	7.4	0.463	2.9	PASS
E047084-57	Bubbler Rm A-213	11/22/2016	07:20	7.4	0.738	1.4	PASS
E047084-58	Bubbler Rm A-212	11/22/2016	07:19	7.4	0.771	2.8	PASS
E047084-59	Bubbler Rm A-221	11/22/2016	07:21	7.4	0.462	3.1	PASS
E047084-60	Bubbler Rm A-220	11/22/2016	07:21	7.4	0.861	1.4	PASS
E047084-61	Bubbler Rm A-210	11/22/2016	07:22	7.3	0.364	1.7	PASS
E047084-62	Bubbler Rm A-211	11/22/2016	07:23	7.3	0.720	2.9	PASS
E047084-63	Bubbler Rm B-123	11/22/2016	06:42	7.3	0.241	6.3	PASS
E047084-64	Fountain B-155 Right	11/22/2016	06:40	7.3	0.439	<1.0	PASS
E047084-65	Fountain B-155 Left	11/22/2016	06:40	7.3	0.412	<1.0	PASS

Eldersburg ES

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047161-01	Dishroom Triple Sink Right	11/30/2016	05:35	6.5	0.193	7.9	PASS
E047161-02	Dishroom Triple Sink Left	11/30/2016	05:35	6.5	0.136	38.9	FAIL
E047161-03	Dishroom Hand Sink	11/30/2016	05:35	6.5	0.205	25.3	FAIL
E047161-04	Kitchen Double Sink	11/30/2016	05:36	6.7	0.129	4.9	PASS
E047161-05	Kitchen Hand Sink	11/30/2016	05:37	6.8	0.251	7.7	PASS
E047161-06	Cafeteria Fountain	11/30/2016	05:38	7.0	0.092	<1.0	PASS
E047161-07	K1 Bubbler	11/30/2016	05:40	7.1	0.101	<1.0	PASS
E047161-08	K2 Bubbler	11/30/2016	05:41	7.2	0.106	<1.0	PASS
E047161-09	K3 Bubbler	11/30/2016	05:41	7.6	0.113	<1.0	PASS
E047161-10	K4 Bubbler	11/30/2016	05:41	7.6	0.104	<1.0	PASS
E047161-11	K5 Bubbler	11/30/2016	05:42	7.7	0.096	1.7	PASS
E047161-12	Room D1 Bubbler	11/30/2016	05:44	7.7	0.165	<1.0	PASS
E047161-13	Room D6 Bubbler	11/30/2016	05:44	7.8	0.151	<1.0	PASS
E047161-14	Room D4 Bubbler	11/30/2016	05:44	7.8	0.324	<1.0	PASS
E047161-15	Room D3 Bubbler	11/30/2016	05:45	7.9	0.272	<1.0	PASS
E047161-16	Room D2 Sink	11/30/2016	05:47	8.1	1.55	<1.0	FAIL
E047161-17	Room E2 Sink	11/30/2016	05:47	8.4	1.12	<1.0	PASS
E047161-18	Room E3 Bubbler	11/30/2016	05:48	8.4	0.091	1.2	PASS
E047161-19	Room E4 Bubbler	11/30/2016	05:48	8.5	0.648	<1.0	PASS
E047161-20	Room E6 Bubbler	11/30/2016	05:49	8.3	0.211	<1.0	PASS
E047161-21	Room E1 Bubbler	11/30/2016	05:49	8.3	0.154	<1.0	PASS
E047161-22	Fountain NC-4	11/30/2016	05:51	8.3	0.062	<1.0	PASS
E047161-23	Room B6 Bubbler	11/30/2016	05:52	8.2	0.145	<1.0	PASS
E047161-24	Room B1 Bubbler	11/30/2016	05:52	8.2	0.150	<1.0	PASS
E047161-25	Room B3 Bubbler	11/30/2016	05:53	8.2	0.272	<1.0	PASS
E047161-26	Room B4 Bubbler	11/30/2016	05:53	8.2	0.324	<1.0	PASS
E047161-27	Room B2 Sink	11/30/2016	05:54	8.3	0.718	<1.0	PASS
E047161-28	Room A2 Sink	11/30/2016	05:55	8.4	0.633	1.1	PASS
E047161-29	Room A3 Bubbler	11/30/2016	05:55	8.3	0.150	<1.0	PASS
E047161-30	Room A4 Bubbler	11/30/2016	05:55	8.3	0.144	<1.0	PASS
E047161-31	Room A6 Bubbler	11/30/2016	05:55	8.2	0.136	<1.0	PASS
E047161-32	Room A1 Bubbler	11/30/2016	05:58	8.2	0.130	<1.0	PASS

Eldersburg ES

E047161-33	Fountain G4	11/30/2016	05:59	8.2	0.045	<1.0	PASS
E047161-34	Room C6 Bubbler	11/30/2016	06:01	8.2	0.150	<1.0	PASS
E047161-35	Room C1 Bubbler	11/30/2016	06:01	8.2	0.161	<1.0	PASS
E047161-36	Room C4 Bubbler	11/30/2016	06:02	8.4	0.552	<1.0	PASS
E047161-37	Room C3 Bubbler	11/30/2016	06:02	8.4	0.459	<1.0	PASS
E047161-38	Room C2 Sink	11/30/2016	06:03	8.5	0.253	<1.0	PASS
E047161-39	Office Hall Sink	11/30/2016	06:04	8.5	0.252	30.9	FAIL
E047161-40	Room AD3 Sink	11/30/2016	06:05	8.4	0.080	4.7	PASS

Elmer Wolfe ES

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047017-01	Dishroom Triple Sink Right	11/16/2016	06:35	7.2	0.591	7.3	PASS
E047017-02	Dishroom Triple Sink Left	11/16/2016	06:35	7.2	0.498	14.5	PASS
E047017-03	Dishroom Hand Sink	11/16/2016	06:37	7.1	0.122	23.0	FAIL
E047017-04	Dishroom Sprayer Right	11/16/2016	06:39	7.0	0.646	15.1	PASS
E047017-05	Dishroom Sprayer Left	11/16/2016	06:40	7.1	0.277	4.1	PASS
E047017-06	Kitchen Double Sink	11/16/2016	06:41	7.2	0.602	18.2	PASS
E047017-07	Kitchen Hand Sink by Double	11/16/2016	06:42	7.1	0.710	8.3	PASS
E047017-08	Kitchen Pot Filler	11/16/2016	06:43	7.1	0.227	92.6	FAIL
E047017-09	Kitchen Hand Sink by Mixer	11/16/2016	06:43	7.1	0.800	15.3	PASS
E047017-10	Fountain Cafeteria Right	11/16/2016	06:46	7.1	0.845	<1.0	PASS
E047017-11	Fountain Cafeteria Left	11/16/2016	06:47	7.0	0.529	1.8	PASS
E047017-12	Fountain Main Hallway Right	11/16/2016	06:48	7.1	0.694	2.0	PASS
E047017-13	Fountain Main Hallway Left	11/16/2016	06:48	6.9	0.653	2.1	PASS
E047017-14	Fountain K/1st Hall Right	11/16/2016	06:51	7.0	0.533	2.2	PASS
E047017-15	Fountain K/1st Hall Left	11/16/2016	06:51	7.1	0.512	2.1	PASS
E047017-16	Fountain 2nd Grade Hall Right	11/16/2016	06:53	7.0	0.699	1.2	PASS
E047017-17	Fountain 2nd Grade Hall Left	11/16/2016	06:53	6.9	0.526	1.1	PASS
E047017-18	Fountain 3rd Grade Hall Right	11/16/2016	06:56	7.0	0.607	1.0	PASS
E047017-19	Fountain 3rd Grade Hall Left	11/16/2016	06:56	7.0	0.479	<1.0	PASS
E047017-20	Fountain 5th Grade Hall Right	11/16/2016	06:58	7.0	0.500	1.2	PASS
E047017-21	Fountain 5th Grade Hall Left	11/16/2016	06:58	7.0	0.759	1.1	PASS

Francis Scott Key HS

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047016-01	Kitchen Hand Sink West	11/16/2016	06:02	7.3	0.382	16.9	PASS
E047016-02	Kitchen Double Sink	11/16/2016	06:03	6.6	0.341	9.1	PASS
E047016-03	Kitchen Hand Sink East	11/16/2016	06:04	6.5	0.398	14.5	PASS
E047016-04	Kitchen Left Pot Filler	11/16/2016	06:05	6.6	0.336	9.6	PASS
E047016-05	Kitchen Right Pot Filler	11/16/2016	06:05	6.6	0.364	5.4	PASS
E047016-06	Kitchen Triple Sink Right	11/16/2016	06:06	6.9	0.329	10.4	PASS
E047016-07	Kitchen Triple Sink Left	11/16/2016	06:06	7.0	0.377	29.7	FAIL
E047016-08	Washroom Hand Sink	11/16/2016	06:08	6.9	0.375	29.7	FAIL
E047016-09	Fountain 500	11/16/2016	06:08	6.9	0.160	<1.0	PASS
E047016-10	Fountain across from 510 Right	11/16/2016	06:09	6.8	0.172	<1.0	PASS
E047016-11	Fountain across from 510 Left	11/16/2016	06:09	6.9	0.146	1.5	PASS
E047016-12	Fountain Room 804 Right	11/16/2016	06:14	7.0	0.084	<1.0	PASS
E047016-13	Fountain Room 804 Left	11/16/2016	06:14	7.0	0.079	<1.0	PASS
E047016-14	Fountain Room 911	11/16/2016	06:15	7.0	0.100	1.0	PASS
E047016-15	Fountain 300 Hall Bath Right	11/16/2016	06:20	7.0	0.096	<1.0	PASS
E047016-16	Fountain 300 Hall Bath Left	11/16/2016	06:20	7.0	0.111	<1.0	PASS
E047016-17	Fountain 200 Hall Bath Right	11/16/2016	06:24	7.0	0.080	<1.0	PASS
E047016-18	Fountain 200 Hall Bath Left	11/16/2016	06:24	7.0	0.082	<1.0	PASS
E047016-19	Fountain Room 601 Gym Right	11/16/2016	06:26	7.0	0.153	<1.0	PASS
E047016-20	Fountain Room 601 Gym Left	11/16/2016	06:26	6.9	0.134	<1.0	PASS
E047016-21	Auditorium Right Fountain	11/16/2016	06:34	7.0	0.153	3.7	PASS
E047016-22	Auditorium Left Fountain	11/16/2016	06:34	7.1	0.172	3.5	PASS
E047016-23	Weight Room Fountain	11/16/2016	06:35	7.0	0.218	<1.0	PASS
E047016-24	Cafetria Fountain	11/16/2016	06:37	6.9	0.527	1.0	PASS
E047016-25	Fountain Shop Room 909	11/16/2016	06:42	6.9	0.272	1.6	PASS
E047016-26	Fountain Band Room 812	11/16/2016	06:46	7.1	0.137	<1.0	PASS

Freedom ES

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047163-01	Fountain Lobby	11/30/2016	07:19	8.1	0.072	<1.0	PASS
E047163-02	Kitchen Right	11/30/2016	07:20	8.0	0.034	2.8	PASS
E047163-03	Kitchen Left	11/30/2016	07:20	8.0	0.080	2.8	PASS
E047163-04	Kitchen Hand Sink	11/30/2016	07:21	8.6	0.071	13.7	PASS
E047163-05	Cafeteria Fountain	11/30/2016	07:22	8.6	0.063	<1.0	PASS
E047163-06	Kindergarten 1S Bubbler	11/30/2016	07:23	8.5	0.090	<1.0	PASS
E047163-07	Kindergarten 2M Bubbler	11/30/2016	07:23	8.5	0.091	<1.0	PASS
E047163-08	Kindergarten 3D Bubbler	11/30/2016	07:24	8.4	0.092	<1.0	PASS
E047163-09	Kindergarten 4K Bubbler	11/30/2016	07:25	8.4	0.086	<1.0	PASS
E047163-10	Art Room Bubbler	11/30/2016	07:26	8.4	0.086	<1.0	PASS
E047163-11	Music Room Bubbler	11/30/2016	07:26	8.3	0.137	1.3	PASS
E047163-12	Instrumental Music Bubbler	11/30/2016	07:27	8.3	0.051	2.2	PASS
E047163-13	Health Bubbler	11/30/2016	07:27	8.3	0.075	1.4	PASS
E047163-14	Primary Hall Fountain	11/30/2016	07:28	8.3	0.099	<1.0	PASS
E047163-15	Fountain by Custodian Closet	11/30/2016	07:28	8.3	0.072	<1.0	PASS
E047163-16	T Hall 3rd Fountain	11/30/2016	07:29	8.3	0.075	<1.0	PASS
E047163-17	T Hall 5th Fountain	11/30/2016	07:29	8.4	0.051	<1.0	PASS
E047163-18	Faculty Lounge Sink	11/30/2016	07:32	8.4	0.071	<1.0	PASS
E047163-19	Nurse Sink	11/30/2016	07:33	8.2	0.059	2.2	PASS

Friendship Valley ES

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047037-01	Hall 115 Fountain Right	11/17/2016	05:48	7.5	0.022	<1.0	PASS
E047037-02	Hall 115 Fountain Left	11/17/2016	05:48	7.7	0.022	<1.0	PASS
E047037-03	Kitchen Single Sink	11/17/2016	05:50	7.8	0.010	1.1	PASS
E047037-04	Kitchen Hand Sink	11/17/2016	05:50	7.7	0.028	20.9	FAIL
E047037-05	Dishwashing Room Sink Right	11/17/2016	05:51	7.7	0.270	12.6	PASS
E047037-06	Dishwashing Room Sink Left	11/17/2016	05:51	7.8	0.034	4.5	PASS
E047037-07	Dishwashing Room Hand Sink	11/17/2016	05:51	7.1	0.390	316	FAIL
E047037-08	Hall 113 Fountain	11/17/2016	05:53	7.4	0.042	<1.0	PASS
E047037-09	Grade 4 Commons Fountain	11/17/2016	05:54	7.7	0.011	<1.0	PASS
E047037-10	Grade 5 Commons Fountain	11/17/2016	05:54	7.9	0.015	<1.0	PASS
E047037-11	Grade 2 Commons Fountain	11/17/2016	05:57	8.0	0.016	<1.0	PASS
E047037-12	Grade 3 Commons Fountain	11/17/2016	05:57	8.1	0.013	<1.0	PASS
E047037-13	Grade K Commons Fountain	11/17/2016	06:00	8.2	0.008	<1.0	PASS
E047037-14	Grade 1 Commons Fountain	11/17/2016	06:00	8.3	0.019	<1.0	PASS
E047037-15	Portable 1132 Fountain	11/17/2016	06:02	8.3	0.014	<1.0	PASS

Gateway School

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047038-01	Kitchen Hand Sink	11/17/2016	06:22	8.3	0.060	7.8	PASS
E047038-02	Kitchen Triple Sink Left	11/17/2016	06:22	8.0	0.328	72.2	FAIL
E047038-04	Kitchen Sprayer	11/17/2016	06:23	7.4	0.553	161	FAIL
E047038-05	Office Water Fountain	11/17/2016	06:25	7.8	0.042	<1.0	PASS
E047038-06	Room 124 Kitchen Sink	11/17/2016	06:26	8.0	0.008	<1.0	PASS
E047038-07	Room 132 Middle School Fountain	11/17/2016	06:27	8.2	0.051	<1.0	PASS
E047038-08	Portable 9 Fountain	11/17/2016	06:28	8.3	0.037	<1.0	PASS
E047038-09	Portable 10 Fountain	11/17/2016	06:28	8.4	0.013	<1.0	PASS
E047038-10	Room 104B Fountain	11/17/2016	06:30	8.4	0.008	<1.0	PASS
E047038-11	Room 112 Kitchen	11/17/2016	06:31	8.4	0.565	7.5	PASS
E047038-12	Food Lab Left Sink	11/17/2016	06:33	8.4	0.013	1.9	PASS
E047038-13	Food Lab Middle Sink	11/17/2016	06:33	8.5	0.054	2.5	PASS
E047038-14	Food Lab Right Sink	11/17/2016	06:33	8.4	0.064	4.5	PASS
E047038-15	Room 159 Health Suite	11/17/2016	06:34	8.3	0.023	2.6	PASS
E047038-16	Room 183 Fountain	11/17/2016	06:35	8.4	0.027	<1.0	PASS

Hampstead ES

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047108-01	Fountain at Entrance	11/23/2016	07:20	7.8	0.147	1.4	PASS
E047108-02	Kitchen Hand Slnk by Serving Line	11/23/2016	07:21	7.9	0.492	26.3	FAIL
E047108-03	Ktchen Pot Filler	11/23/2016	07:22	8.0	0.312	20.3	FAIL
E047108-04	Ktchen Sink	11/23/2016	07:23	8.0	0.231	3.0	PASS
E047108-05	Kitchen Hand Sink	11/23/2016	07:23	8.1	0.437	33.0	FAIL
E047108-06	Washroom Right Slnk	11/23/2016	07:24	8.0	0.352	14.1	PASS
E047108-07	Washroom Left Sink	11/23/2016	07:24	8.0	0.379	52.8	FAIL
E047108-08	Bubbler Rm 123A	11/23/2016	07:27	8.1	0.323	4.8	PASS
E047108-09	Bubbler Rm 122	11/23/2016	07:29	7.6	0.146	4.4	PASS
E047108-10	Bubbler Rm 122A	11/23/2016	07:29	7.6	0.260	5.7	PASS
E047108-11	Bubbler Rm 120A	11/23/2016	07:34	7.7	0.271	11.6	PASS
E047108-12	Bubbler Rm 119A	11/23/2016	07:35	8.0	0.316	7.8	PASS
E047108-13	Fountain by Rm 114	11/23/2016	07:38	8.0	0.398	1.2	PASS
E047108-14	Bubbler Rm 114A	11/23/2016	07:39	8.1	0.294	34.1	FAIL
E047108-15	Bubbler Rm 115	11/23/2016	07:41	8.1	0.252	8.2	PASS
E047108-16	Bubbler Rm 115A	11/23/2016	07:41	8.1	0.328	12.3	PASS
E047108-17	Bubbler Rm 112	11/23/2016	07:43	8.1	0.234	5.7	PASS
E047108-18	Bubbler Rm 112A	11/23/2016	07:44	8.1	0.195	3.2	PASS
E047108-19	Bubbler Rm 111	11/23/2016	07:45	8.1	0.199	7.7	PASS
E047108-20	Bubbler Rm 111A	11/23/2016	07:46	8.1	0.262	7.8	PASS
E047108-21	Bubbler Rm 106A	11/23/2016	07:48	8.1	0.545	7.7	PASS
E047108-22	Bubbler Rm 105	11/23/2016	07:49	8.1	0.314	22.2	FAIL
E047108-23	Buble Rm 105A	11/23/2016	07:50	8.1	0.350	6.5	PASS
E047108-24	Bubbler Rm 103	11/23/2016	07:50	8.1	0.427	26.5	FAIL
E047108-25	Bubbler Rm 102	11/23/2016	07:52	8.1	0.292	21.4	FAIL
E047108-26	Bubbler Rm 100	11/23/2016	07:53	8.1	0.173	83.1	FAIL
E047108-27	Bubbler Rm 107	11/23/2016	07:56	8.2	0.399	<1.0	PASS
E047108-28	Bubbler Rm 108	11/23/2016	07:57	8.4	0.403	<1.0	PASS
E047108-29	Bubbler Rm 109	11/23/2016	07:58	8.2	0.313	2.7	PASS
E047108-30	Sink Rm 136B	11/23/2016	08:02	8.0	0.404	8.8	PASS

Liberty HS

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047162-01	Fountain Outside Rm 428	11/30/2016	06:17	8.3	0.137	<1.0	PASS
E047162-02	Fountain Outside Rm 428 Bottle Filler	11/30/2016	06:17	8.2	0.140	<1.0	PASS
E047162-03	Fountain Outside Rm 429	11/30/2016	06:20	8.1	0.108	<1.0	PASS
E047162-04	Fountain Outside Rm 410	11/30/2016	06:21	8.0	0.127	<1.0	PASS
E047162-05	Fountain Outside Rm 405	11/30/2016	06:22	8.0	0.117	<1.0	PASS
E047162-06	Fountain Left 4th Main Entrance	11/30/2016	06:27	8.0	0.085	<1.0	PASS
E047162-07	Fountain Outside Rm 341	11/30/2016	06:27	8.0	0.154	<1.0	PASS
E047162-08	Kitchen Hand Sink by Walk- In	11/30/2016	06:29	8.0	0.101	5.3	PASS
E047162-09	Kitchen Triple Slnk Right by Entrance	11/30/2016	06:30	7.5	0.169	28.2	FAIL
E047162-10	Kitchen Triple Sink Left by Entrance	11/30/2016	06:30	7.4	0.069	4.6	PASS
E047162-11	Kitchen Pot Filler	11/30/2016	06:31	7.8	0.052	1.5	PASS
E047162-12	Kitchen Triple Slnk Center Right	11/30/2016	06:32	7.8	0.101	1.4	PASS
E047162-13	Kitchen Triple Sink Center Left	11/30/2016	06:32	7.8	0.083	2.9	PASS
E047162-14	Kitchen Hand Sink Center	11/30/2016	06:33	7.8	0.092	2.3	PASS
E047162-15	Kitchen Hand Sink Serving Line left	11/30/2016	06:33	7.6	0.130	37.7	FAIL
E047162-16	Kitchen Hand Sink Serving Line Right	11/30/2016	06:34	7.6	0.088	7.6	PASS
E047162-17	Dishroom Hand Sink	11/30/2016	06:36	7.0	0.390	140	FAIL
E047162-18	Dishroom Sink	11/30/2016	06:36	6.7	0.247	214	FAIL
E047162-19	Fountain Outside Rm 220	11/30/2016	06:38	7.2	0.232	1.1	PASS
E047162-20	Fountain by Lower Level Locker Rm	11/30/2016	06:39	7.8	0.100	<1.0	PASS
E047162-21	Fountain Main Gym 2nd Floor	11/30/2016	06:40	7.9	0.136	<1.0	PASS
E047162-22	Fountain Outside Rm 205 Right	11/30/2016	06:42	7.9	0.104	<1.0	PASS
E047162-23	Fountain Outside Rm 205 Left	11/30/2016	06:42	7.8	0.443	<1.0	PASS

Liberty HS

E047162-24	Fountain Outside Rm 118	11/30/2016	06:44	7.9	0.253	<1.0	PASS
E047162-25	Sink Work Room 411	11/30/2016	06:48	7.9	0.137	2.0	PASS
E047162-26	Fountain Outside Rm 509	11/30/2016	06:49	7.9	0.145	<1.0	PASS
E047162-27	Teachers Lounge Kitchen Sink	11/30/2016	06:51	7.9	0.103	<1.0	PASS
E047162-28	Fountain Between Rm 513-514	11/30/2016	06:51	7.9	0.249	<1.0	PASS
E047162-29	Media Center Fountain	11/30/2016	06:53	7.9	0.132	<1.0	PASS
E047162-30	Rm 119 Sink Station 1	11/30/2016	06:55	7.9	0.097	3.2	PASS
E047162-31	Rm 119 Sink Station 2	11/30/2016	06:55	7.9	0.137	9.2	PASS
E047162-32	Rm 119 Sink Station 3	11/30/2016	06:55	7.9	0.126	7.9	PASS
E047162-33	Rm 119 Sink Station 4	11/30/2016	06:55	8.0	0.111	3.3	PASS
E047162-34	Rm 119 Sink Station 5	11/30/2016	06:55	8.0	0.128	7.3	PASS
E047162-35	Rm 119 Sink Teachers Station	11/30/2016	06:55	8.0	0.102	5.2	PASS
E047162-36	Portable #1 Fountain	11/30/2016	07:00	8.0	0.132	<1.0	PASS

Linton Springs ES

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047146-01	Fountain, A121	11/29/2016	06:43	8.2	0.085	<1.0	PASS
E047146-02	Sink A125	11/29/2016	06:44	8.3	0.080	<1.0	PASS
E047146-03	Fountain, 4-5th grade Hall Right	11/29/2016	06:45	8.3	0.105	<1.0	PASS
E047146-04	Fountain, 4-5th Grade Hall Left	11/29/2016	06:45	8.3	0.121	<1.0	PASS
E047146-05	Fountain, D123	11/29/2016	06:46	8.3	0.116	<1.0	PASS
E047146-06	Fountain, K-1 Hall Right	11/29/2016	06:47	8.3	0.103	<1.0	PASS
E047146-07	Fountain, K-1 Hall Left	11/29/2016	06:47	8.3	0.114	<1.0	PASS
E047146-08	Fountain, 3rd Grade Hall Right	11/29/2016	06:49	8.3	0.119	<1.0	PASS
E047146-09	Fountain, 3rd Grade Hall Left	11/29/2016	06:49	8.4	0.101	<1.0	PASS
E047146-10	Kitchen Hand Sink Front	11/29/2016	06:52	8.0	0.088	1.9	PASS
E047146-11	Kitchen Single Sink	11/29/2016	06:53	8.0	0.071	9.1	PASS
E047146-12	Kitchen Pot Filler	11/29/2016	06:53	8.1	0.040	4.1	PASS
E047146-13	Kitchen Hand Sink Rear	11/29/2016	06:54	7.9	0.246	12.1	PASS
E047146-14	Dishroom Triple Slnk Right	11/29/2016	06:55	8.2	0.082	2.5	PASS
E047146-15	Dishroom Triple Slnk Left	11/29/2016	06:55	8.0	1.12	61.0	FAIL
E047146-16	Dishroom Hand Sink	11/29/2016	06:55	7.5	0.128	57.9	FAIL
E047146-17	Dishroom Spray	11/29/2016	06:56	7.7	0.089	2.4	PASS
E047146-18	Community Room Fountain Right	11/29/2016	07:06	7.8	0.161	<1.0	PASS
E047146-19	Community Room Fountain Left	11/29/2016	07:06	7.8	0.191	<1.0	PASS

Manchester ES

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047087-01	Fountain Entrance	11/22/2016	07:02	7.3	0.677	<1.0	PASS
E047087-02	Kitchen Triple Sink Right	11/22/2016	07:05	7.2	0.387	24.2	FAIL
E047087-03	Kitchen Triple Sink Left	11/22/2016	07:05	7.2	0.379	2.7	PASS
E047087-04	Kitchen Pot Filler	11/22/2016	07:05	7.2	0.807	4.0	PASS
E047087-05	Kitchen Hand Sink	11/22/2016	07:05	7.2	0.601	20.2	FAIL
E047087-06	Cafeteria Fountain	11/22/2016	07:06	7.2	0.606	<1.0	PASS
E047087-07	Teachers Lounge Sink	11/22/2016	07:07	7.2	0.773	1.6	PASS
E047087-08	Bubbler Rm 138	11/22/2016	07:09	7.2	0.291	1.2	PASS
E047087-09	Bubbler Rm 137	11/22/2016	07:10	7.2	0.211	<1.0	PASS
E047087-10	Bubbler Rm 136	11/22/2016	07:10	7.1	0.215	1.5	PASS
E047087-11	Bubbler Rm 222	11/22/2016	07:11	7.1	0.230	2.7	PASS
E047087-12	Bubbler Rm 223	11/22/2016	07:12	7.1	0.270	5.8	PASS
E047087-13	Bubbler Rm 224	11/22/2016	07:13	7.2	0.396	2.3	PASS
E047087-14	Fountain between Rm 106 & 107	11/22/2016	07:15	7.2	0.171	<1.0	PASS
E047087-15	Bubbler Rm 150	11/22/2016	07:16	7.2	1.34	5.4	FAIL
E047087-16	Bubbler Rm 141	11/22/2016	07:17	7.2	0.706	5.2	PASS
E047087-17	Bubbler Rm 149	11/22/2016	07:17	7.1	0.661	5.7	PASS
E047087-18	Bubbler Rm 142	11/22/2016	07:18	7.2	0.561	3.7	PASS
E047087-19	Bubbler Rm 148	11/22/2016	07:19	7.2	1.35	4.0	FAIL
E047087-20	Bubbler Rm 143	11/22/2016	07:20	7.1	0.518	5.0	PASS
E047087-21	Bubbler Rm 147	11/22/2016	07:20	7.1	0.796	2.9	PASS
E047087-22	Bubbler Rm 144	11/22/2016	07:21	7.1	0.635	3.9	PASS
E047087-23	Bubbler Rm 146	11/22/2016	07:21	7.1	0.853	5.3	PASS
E047087-24	Bubbler Rm 196	11/22/2016	07:24	7.1	0.783	3.9	PASS
E047087-25	Bubbler Rm 195	11/22/2016	07:25	7.1	0.782	4.1	PASS
E047087-26	Bebbler Rm 194	11/22/2016	07:26	7.1	0.790	2.9	PASS
E047087-27	Bubbler Rm 193	11/22/2016	07:27	7.1	0.493	3.0	PASS
E047087-28	Bubbler Rm 191	11/22/2016	07:30	7.0	0.391	2.2	PASS
E047087-29	Bubbler Rm 188	11/22/2016	07:30	7.1	0.367	2.9	PASS
E047087-30	Bubbler Rm 189	11/22/2016	07:31	7.0	0.331	2.4	PASS
E047087-31	Bubbler Rm 186	11/22/2016	07:32	7.1	0.459	<1.0	PASS
E047087-32	Bubbler Rm 185	11/22/2016	07:33	7.1	0.604	3.6	PASS

Manchester ES

E047087-33	Bubbler Rm 184	11/22/2016	07:34	7.1	0.554	3.0	PASS
E047087-34	Bubbler Rm 183	11/22/2016	07:35	7.1	0.632	<1.0	PASS
E047087-35	Bubbler Rm 182	11/22/2016	07:35	7.1	0.823	4.4	PASS
E047087-36	Bubbler Rm 169	11/22/2016	07:36	7.1	1.04	4.4	PASS
E047087-37	Bubbler Rm 168	11/22/2016	07:37	7.1	0.621	5.6	PASS
E047087-38	Bubbler Rm 167	11/22/2016	07:38	7.1	1.02	3.1	PASS
E047087-39	Bubbler Rm 166	11/22/2016	07:38	7.1	1.07	2.2	PASS
E047087-40	Sink Rm 161	11/22/2016	07:40	7.0	0.735	8.4	PASS
E047087-41	Sink Rm 160	11/22/2016	07:41	7.1	0.367	6.6	PASS
E047087-42	Sink Rm 199F	11/22/2016	07:42	7.1	0.535	16.3	PASS

Manchester Valley HS

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047085-01	Kitchen Hand Sink Food Line East	11/22/2016	05:55	7.2	0.463	11.2	PASS
E047085-02	Kitchen Hand Sink by Walk-In	11/22/2016	00:56	7.2	0.553	42.5	FAIL
E047085-03	Kitchen Double Sink	11/22/2016	05:57	7.2	0.434	3.4	PASS
E047085-04	Kitchen Hand Sink with Eye Wash	11/22/2016	05:57	7.1	0.449	37.1	FAIL
E047085-05	Kitchen Hand Sink Food Line West	11/22/2016	05:58	7.2	0.394	9.5	PASS
E047085-06	Dishroom Hand Sink	11/22/2016	05:59	7.2	0.690	30.2	FAIL
E047085-07	Dishroom Triple Sink Right	11/22/2016	05:59	7.2	0.342	27.5	FAIL
E047085-08	Dishroom Triple Sink Left	11/22/2016	05:59	7.2	0.425	8.7	PASS
E047085-09	Staff Dining Rm Sink	11/22/2016	06:02	7.2	0.303	6.5	PASS
E047085-10	Fountain C Wing 2nd Floor Right	11/22/2016	06:05	7.2	0.182	<1.0	PASS
E047085-11	Fountain C Wing 2nd Floor Left	11/22/2016	06:05	7.2	0.174	<1.0	PASS
E047085-12	Fountain A Wing 2nd Floor Right	11/22/2016	06:06	7.2	0.224	<1.0	PASS
E047085-13	Fountain A Wing 2nd Floor Left	11/22/2016	06:06	7.2	0.227	<1.0	PASS
E047085-14	Fountain A Wing 1st Floor Right	11/22/2016	06:08	7.2	0.159	<1.0	PASS
E047085-15	Fountain A Wing 1st Floor Left	11/22/2016	06:08	7.2	0.177	<1.0	PASS
E047085-16	Fountain D Wing 1st Floor Right	11/22/2016	06:10	7.2	0.197	<1.0	PASS
E047085-17	Fountain D Wing 1st Floor Left	11/22/2016	06:10	7.2	0.209	<1.0	PASS
E047085-18	Room D121 Sink	11/22/2016	06:10	7.2	0.476	6.1	PASS
E047085-19	Room D121 Cooler Fill Tap	11/22/2016	06:10	7.2	0.308	4.8	PASS
E047085-20	Fountain D130	11/22/2016	06:12	7.2	0.258	<1.0	PASS
E047085-21	Fountain D123	11/22/2016	06:12	7.2	0.314	<1.0	PASS
E047085-22	Fountain D113	11/22/2016	06:13	7.2	0.367	<1.0	PASS
E047085-23	Fountain D104	11/22/2016	06:14	7.2	0.232	<1.0	PASS

Manchester Valley HS

E047085-24	Fountain C Wing 1st Floor Right	11/22/2016	06:16	7.2	0.190	<1.0	PASS
E047085-25	Fountain C Wing 1st Floor Left	11/22/2016	06:16	7.2	0.194	<1.0	PASS

Mechanicsville ES

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047273-01	Kitchen Pot Filler	12/07/2016	06:24	7.2	0.097	22.6	FAIL
E047273-02	Kitchen Double Sink Right	12/07/2016	06:25	6.9	0.419	4.2	PASS
E047273-03	Kitchen Double Sink Left	12/07/2016	06:25	6.9	0.377	18.5	PASS
E047273-04	Kitchen Jug Filler	12/07/2016	06:26	6.4	0.515	366	FAIL
E047273-05	Dishroom Triple Sink Right	12/07/2016	06:26	6.6	0.153	10.1	PASS
E047273-06	Dishroom Triple Sink Left	12/07/2016	06:26	6.6	0.329	56.1	FAIL
E047273-07	Dishroom Hand Sink	12/07/2016	06:27	6.6	4.06	164	FAIL
E047273-08	Cafeteria Fountain by Kitchen	12/07/2016	06:28	6.7	0.986	2.5	PASS
E047273-09	Cafeteria Fountain by Entrance	12/07/2016	06:28	6.8	0.765	<1.0	PASS
E047273-10	Office Workroom Sink	12/07/2016	06:30	6.8	0.390	<1.0	PASS
E047273-11	Nurse's Office Sink	12/07/2016	06:33	6.8	0.682	4.1	PASS
E047273-12	Fountain Lobby	12/07/2016	06:34	6.8	0.497	<1.0	PASS
E047273-13	Fountain by Rm 149	12/07/2016	06:35	6.8	0.723	<1.0	PASS
E047273-14	Bubbler Rm 201	12/07/2016	06:37	6.8	0.710	1.3	PASS
E047273-15	Bubbler Rm 202	12/07/2016	06:37	6.8	0.730	2.0	PASS
E047273-16	Bubbler Rm 203	12/07/2016	06:38	6.8	0.763	2.0	PASS
E047273-17	Fountain by Rm 176 Right	12/07/2016	06:40	6.8	0.480	<1.0	PASS
E047273-18	Fountain by Rm 176 Center	12/07/2016	06:40	6.8	0.753	<1.0	PASS
E047273-19	Fountain by Rm 176 Left	12/07/2016	06:40	6.8	0.437	<1.0	PASS
E047273-20	Fountain by Rm 028	12/07/2016	06:43	6.6	0.550	<1.0	PASS
E047273-21	Fountain by Rm 016	12/07/2016	06:44	6.7	0.672	<1.0	PASS
E047273-22	Portable 1 Fountain	12/07/2016	06:45	6.7	0.553	<1.0	PASS
E047273-23	Portable 2 Fountain	12/07/2016	06:46	6.8	0.215	<1.0	PASS
E047273-24	Sink Rm 158	12/07/2016	06:49	7.0	0.099	3.1	PASS

Mt Airy ES

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047063-01	Kitchen Triple Slnk Right	11/18/2016	06:30	7.3	0.172	2.7	PASS
E047063-02	Kitchen Triple Slnk Left	11/18/2016	06:30	7.2	0.133	5.0	PASS
E047063-03	Kitchen Hand Sink by Office	11/18/2016	06:31	7.1	0.222	58.7	FAIL
E047063-04	Dishroom Sprayer	11/18/2016	06:31	7.1	0.207	11.0	PASS
E047063-05	Fountain Cafeteria	11/18/2016	06:32	7.1	0.420	<1.0	PASS
E047063-06	Fountain Outside Gym	11/18/2016	06:34	7.2	0.193	<1.0	PASS
E047063-07	Fountain by Rm 122	11/18/2016	06:36	7.2	0.267	<1.0	PASS
E047063-08	Fountain by Media Center	11/18/2016	06:39	7.2	0.266	<1.0	PASS
E047063-09	Fountain by Rm 222	11/18/2016	06:40	7.3	0.303	<1.0	PASS
E047063-10	Bubbler Rm 226	11/18/2016	06:42	7.3	0.226	4.2	PASS
E047063-11	Bubbler Rm 228	11/18/2016	06:43	7.3	0.215	<1.0	PASS
E047063-12	Bubbler Rm 232	11/18/2016	06:44	7.3	0.236	2.8	PASS
E047063-13	Bubbler Rm 229	11/18/2016	06:46	7.3	0.222	2.6	PASS
E047063-14	Bubbler Rm 233	11/18/2016	06:47	7.4	0.265	1.8	PASS
E047063-15	Bubbler Rm 214	11/18/2016	06:51	7.4	0.284	3.5	PASS
E047063-16	Bubbler Rm 204	11/18/2016	06:53	7.3	0.208	2.2	PASS
E047063-17	Bubbler Rm 203	11/18/2016	06:54	7.4	0.132	1.2	PASS
E047063-18	Bubbler Rm 202	11/18/2016	06:55	7.3	0.150	1.3	PASS
E047063-19	Bubbler Rm 201	11/18/2016	06:57	7.3	0.152	1.1	PASS
E047063-20	Bubbler Rm 301	11/18/2016	06:58	7.4	0.243	1.6	PASS
E047063-21	Bubbler Rm 302	11/18/2016	06:59	7.4	0.237	<1.0	PASS
E047063-22	Bubbler Rm 303	11/18/2016	07:01	7.3	0.257	1.7	PASS
E047063-23	Bubbler Rm 304	11/18/2016	07:02	7.3	0.237	1.1	PASS
E047063-24	Fountain by Rm 304	11/18/2016	07:04	7.3	0.348	<1.0	PASS
E047063-25	Bubbler Rm 313	11/18/2016	07:05	7.4	0.197	1.1	PASS
E047063-26	Bubbler Rm 314	11/18/2016	07:06	7.3	0.213	1.3	PASS
E047063-27	Bubbler Rm 112	11/18/2016	07:10	7.4	0.226	1.5	PASS
E047063-28	Bubbler Rm 110	11/18/2016	07:17	7.4	0.145	2.2	PASS
E047063-29	Bubbler Speech	11/18/2016	07:18	7.4	0.267	8.3	PASS
E047063-30	Bubbler Rm 101	11/18/2016	07:19	7.4	0.241	2.6	PASS
E047063-31	Fountain Portable 1131 Sout	11/18/2016	07:24	7.4	0.645	<1.0	PASS
E047063-32	Fountain Portable 2213 Nort	11/18/2016	07:26	7.4	0.688	1.2	PASS

Mt Airy Middle

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047064-01	8th Grade Fountain Right	11/18/2016	07:38	7.5	0.445	<1.0	PASS
E047064-02	8th Grade Fountain Left	11/18/2016	07:38	7.5	0.490	<1.0	PASS
E047064-03	Kitchen Hand Sink by Food Line Left	11/18/2016	07:41	7.4	0.297	6.8	PASS
E047064-04	Dishroom Hand Sink	11/18/2016	07:42	7.4	0.040	7.2	PASS
E047064-05	Dishroom Triple Sink Right	11/18/2016	07:43	7.5	0.383	2.1	PASS
E047064-06	Dishroom Triple Sink Left	11/18/2016	07:43	7.5	0.382	2.1	PASS
E047064-07	Kitchen Hand Sink by Food Line Right	11/18/2016	07:44	7.4	0.416	<1.0	PASS
E047064-08	Kitchen Triple Sink	11/18/2016	07:44	7.5	0.778	1.4	PASS
E047064-09	Kitchen Hand Sink by Triple Sink	11/18/2016	07:45	7.4	0.734	<1.0	PASS
E047064-10	Cafeteria Fountain Right	11/18/2016	07:46	7.4	0.556	<1.0	PASS
E047064-11	Cafeteria Fountain Left	11/18/2016	07:46	7.4	0.619	<1.0	PASS
E047064-12	Staff Lounge Sink	11/18/2016	07:47	7.4	0.658	<1.0	PASS
E047064-13	Fountain 6th Grade Hall Right	11/18/2016	07:48	7.4	0.437	<1.0	PASS
E047064-14	Fountain 6th Grade Hall Left	11/18/2016	07:48	7.4	0.535	<1.0	PASS
E047064-15	Sink B219	11/18/2016	07:49	7.4	0.522	<1.0	PASS
E047064-16	Fountain 7th Grade Hall Right	11/18/2016	07:52	7.4	0.517	<1.0	PASS
E047064-17	Fountain 7th Grade Hall Left	11/18/2016	07:52	7.4	0.530	<1.0	PASS
E047064-18	Sink A226	11/18/2016	07:53	7.3	0.827	<1.0	PASS
E047064-19	Fountain Specials Hall Right	11/18/2016	07:55	7.4	0.657	<1.0	PASS
E047064-20	Fountain Specials Hall Left	11/18/2016	07:55	7.4	0.692	<1.0	PASS
E047064-21	Sink B130	11/18/2016	07:56	7.4	0.508	1.2	PASS
E047064-22	Fountain Fitness Hall Right	11/18/2016	07:58	7.4	0.627	<1.0	PASS
E047064-23	Fountain Fitness Hall Left	11/18/2016	07:58	7.4	0.603	<1.0	PASS
E047064-24	Sink B118	11/18/2016	08:00	7.4	1.10	<1.0	PASS
E047064-25	Room 106 Station 1 Sink	11/18/2016	08:05	7.4	0.550	<1.0	PASS
E047064-26	Room 106 Station 2 Sink	11/18/2016	08:05	7.3	0.054	<1.0	PASS

Mt Airy Middle

E047064-27	Room 106 Station 3 Sink	11/18/2016	08:05	7.4	0.038	<1.0	PASS
E047064-28	Room 106 Station 4 Sink	11/18/2016	08:05	7.4	0.064	<1.0	PASS
E047064-29	Room 106 Station 5 Sink	11/18/2016	08:05	7.4	0.047	<1.0	PASS
E047064-30	Room 106 Station 6 Sink	11/18/2016	08:05	7.4	0.061	<1.0	PASS
E047064-31	Room 106 Station 7 Sink	11/18/2016	08:05	7.4	0.069	1.4	PASS
E047064-32	Room 106 Teachers Station S	11/18/2016	08:05	7.4	0.128	<1.0	PASS
E047064-33	Room A143 Sink	11/18/2016	08:09	7.4	0.581	<1.0	PASS

North Carroll Middle

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047086-01	Fountain Entrance Right	11/22/2016	06:25	7.3	0.267	<1.0	PASS
E047086-02	Fountain Entrance Left	11/22/2016	06:25	7.5	0.247	<1.0	PASS
E047086-03	Fountain by Gym Right	11/22/2016	06:28	7.5	0.267	<1.0	PASS
E047086-04	Fountain by Gym Left	11/22/2016	06:28	7.6	0.286	<1.0	PASS
E047086-05	Fountain Outside Cafeteria Right	11/22/2016	06:29	7.6	0.181	<1.0	PASS
E047086-06	Fountain Outside Cafeteria Left	11/22/2016	06:29	7.6	0.173	<1.0	PASS
E047086-07	Kitchen Hand Sink by Serving Line	11/22/2016	06:30	7.6	0.361	31.3	FAIL
E047086-08	Dishroom Hand Sink	11/22/2016	06:30	7.6	0.286	26.2	FAIL
E047086-09	Dishroom Triple Sink Right	11/22/2016	06:31	7.4	0.234	51.1	FAIL
E047086-10	Dishroom Triple Sink Left	11/22/2016	06:31	7.5	0.331	8.1	PASS
E047086-11	Kitchen Double Sink	11/22/2016	06:33	7.6	0.400	8.2	PASS
E047086-12	Kitchen Hand Sink by Double Sink	11/22/2016	06:33	7.6	0.323	30.2	FAIL
E047086-13	Kitchen Pot Filler	11/22/2016	06:34	7.1	5.37	18.8	FAIL
E047086-14	Fountain Rm 010 Girls Locker	11/22/2016	06:35	7.1	0.099	<1.0	PASS
E047086-15	Fountain Rm 012 Boys locker	11/22/2016	06:36	7.4	0.277	<1.0	PASS
E047086-16	Sink Rm 148 Faculty Lounge	11/22/2016	06:38	7.5	0.155	2.5	PASS
E047086-17	Fountain Rm 201	11/22/2016	06:40	7.6	0.283	1.8	PASS
E047086-18	Fountain Across Rm 204 Right	11/22/2016	06:41	7.6	0.150	<1.0	PASS
E047086-19	Fountain Across Rm 204 Left	11/22/2016	06:41	7.6	0.170	<1.0	PASS
E047086-20	Fountain by Rm 315 Right	11/22/2016	06:45	7.5	0.212	<1.0	PASS
E047086-21	Fountain by Rm 315 Left	11/22/2016	06:45	7.5	0.221	<1.0	PASS

Northwest Middle

Northwest Middle School							
Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E046993-01	Hand Sink Cafeteria Entance	11/15/2016	06:57	7.4	0.217	19.3	PASS
E046993-02	Cafeteria Triple Sink Left	11/15/2016	06:57	7.4	0.310	8.3	PASS
E046993-03	Cafeteria Triple Sink Right	11/15/2016	06:57	7.4	0.527	45.3	FAIL
E046993-04	Cafeteria Double Sink	11/15/2016	06:58	7.4	0.398	3.7	PASS
E046993-05	Cafeteria Hand Sink by Double Sink	11/15/2016	06:58	7.4	0.281	8.0	PASS
E046993-06	Cafeteria Island Sink by Walk-In Coolers	11/15/2016	06:59	7.4	0.511	113	FAIL
E046993-07	Dishroom Hand Sink	11/15/2016	06:59	7.4	1.24	60.3	FAIL
E046993-08	Dishroom Sprayer	11/15/2016	07:00	7.4	0.527	7.8	PASS
E046993-09	Home Ec Rm 505 Sink #5	11/15/2016	07:04	7.4	0.362	7.7	PASS
E046993-10	Home Ec Rm 505 Sink #4	11/15/2016	07:04	7.4	0.323	12.4	PASS
E046993-11	Home Ec Rm 505 Sink #3	11/15/2016	07:05	7.6	0.337	12.2	PASS
E046993-12	Home Ec Rm 505 Sink #2	11/15/2016	07:05	7.4	0.337	15.5	PASS
E046993-13	Home Ec Rm 505 Sink #1	11/15/2016	07:05	7.4	0.368	9.7	PASS
E046993-14	Home Ec Rm 505 Sink #6	11/15/2016	07:06	7.4	0.339	9.5	PASS
E046993-15	Home Ec Rm 508	11/15/2016	07:06	7.4	0.300	25.7	FAIL
E046993-16	Fountain by Room 517	11/15/2016	07:08	7.4	0.198	<1.0	PASS
E046993-17	8th Grade Fountain	11/15/2016	07:09	7.4	0.237	<1.0	PASS
E046993-18	Fountain by Gym	11/15/2016	07:11	7.5	0.215	<1.0	PASS
E046993-19	Fountain by Library	11/15/2016	07:12	7.5	0.306	<1.0	PASS
E046993-20	7th Grade Fountain	11/15/2016	07:13	7.5	0.126	<1.0	PASS
E046993-21	Fountain Room 209	11/15/2016	07:14	7.5	0.328	<1.0	PASS
E046993-22	Sink Room 209	11/15/2016	07:14	7.5	0.223	4.1	PASS
E046993-23	Sink Main Office	11/15/2016	07:15	7.5	0.154	6.8	PASS

Northwest Middle

Oklahoma Roads Middle

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047164-01	Fountain Lobby Right	11/30/2016	07:22	8.3	0.073	<1.0	PASS
E047164-02	Fountain Lobby Left	11/30/2016	07:22	8.3	0.073	<1.0	PASS
E047164-03	Dishroom Sink Right	11/30/2016	07:26	6.9	0.346	264	FAIL
E047164-04	Dishroom Sink Left	11/30/2016	07:26	7.5	0.057	4.7	PASS
E047164-05	Dishroom Hand Sink	11/30/2016	07:27	7.4	0.173	7.7	PASS
E047164-06	Kitchen Hand Sink	11/30/2016	07:28	7.5	0.088	19.5	PASS
E047164-07	Kitchen Double Sink	11/30/2016	07:29	7.9	0.041	<1.0	PASS
E047164-08	Kitchen Pot Filler	11/30/2016	07:29	8.3	0.078	2.7	PASS
E047164-09	Cafeteria Fountain Right	11/30/2016	07:31	8.3	0.075	<1.0	PASS
E047164-10	Cafeteria Fountain Left	11/30/2016	07:31	8.4	0.071	<1.0	PASS
E047164-11	Faculty Lounge	11/30/2016	07:32	8.4	0.105	<1.0	PASS
E047164-12	Office Kitchen	11/30/2016	07:35	8.4	0.073	1.2	PASS
E047164-13	Fountain by Rm 153	11/30/2016	07:36	8.6	0.070	<1.0	PASS
E047164-14	Fountain by Rm 171	11/30/2016	07:37	8.7	0.076	<1.0	PASS
E047164-15	Fountain by Rm 192	11/30/2016	07:39	8.7	0.069	<1.0	PASS
E047164-16	Fountain by Rm 301	11/30/2016	07:40	8.8	0.093	<1.0	PASS
E047164-17	Fountain by Rm 323	11/30/2016	07:41	8.8	0.075	<1.0	PASS
E047164-18	Fountain by Rm 290	11/30/2016	07:43	8.8	0.068	<1.0	PASS
E047164-19	Fountain by Rm 269	11/30/2016	07:44	8.8	0.075	<1.0	PASS
E047164-20	Fountain by Rm 250	11/30/2016	07:46	8.9	0.067	<1.0	PASS
E047164-21	Fountain by Rm 205 Right	11/30/2016	07:47	8.8	0.068	<1.0	PASS
E047164-22	Fountain by Rm 205 Left	11/30/2016	07:47	8.9	0.073	<1.0	PASS
E047164-23	Fountain Girls Locker Rm	11/30/2016	07:49	8.9	0.070	<1.0	PASS
E047164-24	Fountain Boys Locker Rm	11/30/2016	07:50	8.9	0.076	<1.0	PASS

Parrs Ridge ES

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047062-01	Kitchen Hand Sink	11/18/2016	06:15	6.9	0.637	9.2	PASS
E047062-02	Kitchen Triple Sink	11/18/2016	06:17	7.0	0.320	23.6	FAIL
E047062-03	Kitchen Serving Line Slnk	11/18/2016	06:18	7.0	0.717	2.0	PASS
E047062-04	Kitchen Rear Hand Sink	11/18/2016	06:20	7.1	0.343	2.1	PASS
E047062-05	Dishroom Hand Sink	11/18/2016	06:22	7.1	1.26	56.9	FAIL
E047062-06	Fountain Cafeteria	11/18/2016	06:25	7.2	1.13	<1.0	PASS
E047062-07	Bubbler Rm D-122	11/18/2016	06:30	7.2	0.733	1.1	PASS
E047062-08	Bubbler Rm D-121	11/18/2016	06:31	7.2	0.733	<1.0	PASS
E047062-09	Bubbler Rm D-120	11/18/2016	06:33	7.2	0.742	<1.0	PASS
E047062-10	Bubbler Rm D-119	11/18/2016	06:34	7.2	0.754	<1.0	PASS
E047062-11	Fountain Rm D-118	11/18/2016	06:35	7.2	0.697	<1.0	PASS
E047062-12	Bubbler Rm D-111	11/18/2016	06:37	7.2	0.826	<1.0	PASS
E047062-13	Bubbler Rm D-112	11/18/2016	06:38	7.2	0.735	<1.0	PASS
E047062-14	Bubbler Rm D-110	11/18/2016	06:38	7.4	0.082	1.5	PASS
E047062-15	Bubbler Rm D-109	11/18/2016	06:39	7.5	0.040	6.7	PASS
E047062-16	Bubbler Rm D-105	11/18/2016	06:40	7.5	0.476	1.1	PASS
E047062-17	Bubbler Rm D-103	11/18/2016	06:41	7.5	0.664	<1.0	PASS
E047062-18	Bubbler Rm D-106	11/18/2016	06:42	7.6	0.077	<1.0	PASS
E047062-19	Bubbler Rm D-104	11/18/2016	06:42	7.6	0.749	<1.0	PASS
E047062-20	Fountain Rm D-102	11/18/2016	06:43	7.5	0.472	<1.0	PASS
E047062-21	Bubbler Rm D-096	11/18/2016	06:45	7.4	0.617	<1.0	PASS
E047062-22	Bubbler Rm D-094	11/18/2016	06:46	7.4	0.691	1.1	PASS
E047062-23	Bubbler Rm D-095	11/18/2016	06:47	7.4	0.729	<1.0	PASS
E047062-24	Bubbler Rm D-093	11/18/2016	06:47	7.4	0.792	<1.0	PASS
E047062-25	Bubbler Rm B-064	11/18/2016	06:50	7.4	0.378	1.4	PASS
E047062-26	Bubbler Rm D-062	11/18/2016	06:51	7.4	0.031	1.6	PASS
E047062-27	Fountain Rm B-051	11/18/2016	06:52	7.5	0.605	1.4	PASS
E047062-28	Bubbler Rm B-046	11/18/2016	06:55	7.5	0.260	1.4	PASS
E047062-29	Bubbler Rm B-048	11/18/2016	06:54	7.5	0.273	<1.0	PASS
E047062-30	Bubbler Rm C-068B	11/18/2016	06:58	7.4	0.335	1.2	PASS
E047062-31	Bubbler Rm C-068A	11/18/2016	06:58	7.4	0.513	1.3	PASS
E047062-32	Bubbler Rm C-069	11/18/2016	07:00	7.4	0.445	1.1	PASS

Parrs Ridge ES

E047062-33	Bubbler Rm C-074	11/18/2016	07:01	7.4	0.711	<1.0	PASS
E047062-34	Bubbler Rm C-073	11/18/2016	07:02	7.4	0.624	1.2	PASS
E047062-35	Bubbler Rm C-078	11/18/2016	07:03	7.4	0.695	<1.0	PASS
E047062-36	Bubbler Rm C-077	11/18/2016	07:04	7.4	0.627	<1.0	PASS
E047062-37	Bubbler Rm C-083	11/18/2016	07:05	7.4	0.796	1.7	PASS
E047062-38	Bubbler Rm C-086	11/18/2016	07:06	7.4	0.707	1.9	PASS
E047062-39	Bubbler Rm C-087	11/18/2016	07:07	7.4	0.697	2.2	PASS
E047062-40	Bubbler Rm C-090	11/18/2016	07:00	7.4	0.734	1.2	PASS
E047062-41	Bubbler Rm C-037	11/18/2016	07:12	7.3	0.309	1.3	PASS
E047062-42	Fountain Rm B-063	11/18/2016	07:13	7.3	0.456	<1.0	PASS
E047062-43	Bubbler Rm A-004	11/18/2016	07:14	7.3	0.505	<1.0	PASS

Piney Ridge ES

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047184-01	Dishroom Triple Sink Left	12/01/2016	07:17	7.0	0.327	1450	FAIL
E047184-02	Dishroom Triple Sink Right	12/01/2016	07:17	7.2	1.16	89.0	FAIL
E047184-03	Dishroom Hand Sink	12/01/2016	07:18	7.0	0.162	68.6	FAIL
E047184-04	Kitchen Hand Sink	12/01/2016	07:19	7.2	0.088	1.9	PASS
E047184-05	Kitchen Hand Sink by Serving Line	12/01/2016	07:20	7.0	0.210	93.9	FAIL
E047184-06	Kitchen Pot Filler	12/01/2016	07:20	7.4	0.078	1.1	PASS
E047184-07	Staff Room	12/01/2016	07:22	7.4	0.078	<1.0	PASS
E047184-08	Fountain 1st Floor by Room 101	12/01/2016	07:23	7.6	0.066	<1.0	PASS
E047184-09	Fountain in Cafeteria	12/01/2016	07:24	7.6	0.122	<1.0	PASS
E047184-10	Fountain by Room 116	12/01/2016	07:25	7.7	0.051	<1.0	PASS
E047184-11	Fountain by 2nd Floor Elevator	12/01/2016	07:26	7.7	0.119	<1.0	PASS
E047184-12	Sink Nurses Office	12/01/2016	07:27	7.7	0.139	3.6	PASS
E047184-13	Fountain by Room 314	12/01/2016	07:29	7.8	0.066	<1.0	PASS
E047184-14	Fountain by Room 301	12/01/2016	07:30	7.9	0.079	<1.0	PASS

Robert Moton ES

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047039-01	A25 Bubbler	11/17/2016	06:49	8.4	0.038	<1.0	PASS
E047039-02	A26 Bubbler	11/17/2016	06:49	8.4	0.049	<1.0	PASS
E047039-03	A27 Bubbler	11/17/2016	06:50	8.3	0.074	<1.0	PASS
E047039-04	A28 Bubbler	11/17/2016	06:50	8.2	0.055	<1.0	PASS
E047039-05	D1 Bubbler	11/17/2016	06:52	8.2	0.338	1.2	PASS
E047039-06	D4 Bubbler	11/17/2016	06:52	8.1	0.336	<1.0	PASS
E047039-07	D3 Bubbler	11/17/2016	06:54	8.1	0.072	<1.0	PASS
E047039-08	D2 Bubbler	11/17/2016	06:54	8.0	0.633	<1.0	PASS
E047039-09	Fountain Right Between C-6 & C-9	11/17/2016	06:57	8.0	0.044	<1.0	PASS
E047039-10	Fountain Left Between C-6 & C-9	11/17/2016	06:57	7.9	0.060	<1.0	PASS
E047039-11	E1 Bubbler	11/17/2016	06:58	7.9	0.136	<1.0	PASS
E047039-12	E4 Bubbler	11/17/2016	06:58	8.0	0.051	<1.0	PASS
E047039-13	E3 Bubbler	11/17/2016	06:58	8.0	0.075	<1.0	PASS
E047039-14	E2 Bubbler	11/17/2016	07:00	8.0	0.168	1.3	PASS
E047039-15	F2 Bubbler	11/17/2016	07:00	8.0	0.161	<1.0	PASS
E047039-16	F3 Bubbler	11/17/2016	07:00	8.0	0.050	<1.0	PASS
E047039-17	F1 Bubbler	11/17/2016	07:00	8.0	0.064	<1.0	PASS
E047039-18	F4 Bubbler	11/17/2016	07:00	8.0	0.060	<1.0	PASS
E047039-19	G3 Bubbler	11/17/2016	07:02	8.0	0.103	<1.0	PASS
E047039-20	G2 Bubbler	11/17/2016	07:02	8.0	0.100	<1.0	PASS
E047039-21	G1 Bubbler	11/17/2016	07:02	7.9	0.085	<1.0	PASS
E047039-22	G4 Bubbler	11/17/2016	07:02	7.9	0.133	<1.0	PASS
E047039-23	Fountain Right Between C10 & C8	11/17/2016	07:04	7.9	0.036	<1.0	PASS
E047039-24	Fountain Left Between C10 & C8	11/17/2016	07:04	7.9	0.033	<1.0	PASS
E047039-25	H3 Bubbler	11/17/2016	07:06	8.0	0.063	<1.0	PASS
E047039-26	H2 Bubbler	11/17/2016	07:06	8.0	0.132	<1.0	PASS
E047039-27	H1 Bubbler	11/17/2016	07:06	8.0	0.069	<1.0	PASS
E047039-28	H4 Bubbler	11/17/2016	07:06	8.0	0.097	<1.0	PASS
E047039-29	Faculty Break Room	11/17/2016	07:08	8.0	0.015	<1.0	PASS
E047039-30	Fountain Outside Cafeteria	11/17/2016	07:09	7.9	0.027	<1.0	PASS

Robert Moton ES

E047039-31	Kitchen Hand Sink	11/17/2016	07:14	7.8	0.107	23.2	FAIL
E047039-32	Kitchen Double Sink Right	11/17/2016	07:14	7.4	0.446	105	FAIL
E047039-33	Kitchen Double Sink Left	11/17/2016	07:14	7.4	0.045	12.7	PASS
E047039-34	Kitchen M-2 Hand Sink	11/17/2016	07:15	7.5	0.026	1.9	PASS
E047039-35	Kitchen M-2 Hand Sprayer	11/17/2016	07:15	7.7	0.067	2.7	PASS

Runnymede ES

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E046991-01	Kitchen Prep Sink	11/15/2016	5:49	6.9	0.509	13.5	PASS
E046991-02	Dishroom Double Sink Right	11/15/2016	5:51	6.9	0.534	19.0	PASS
E046991-03	Dishroom Double Sink Left	11/15/2016	5:51	6.9	0.447	27.9	FAIL
E046991-04	Dishroom Hand Sink	11/15/2016	5:52	6.9	0.685	49.0	FAIL
E046991-05	Dishroom Spray Left	11/15/2016	5:53	6.9	0.427	2.7	PASS
E046991-06	Dishroom Spray Right	11/15/2016	5:54	6.9	0.230	2.4	PASS
E046991-07	Kitchen Hand Sink	11/15/2016	5:55	6.8	0.428	33.2	FAIL
E046991-08	Cafeteria Fountain	11/15/2016	5:56	6.8	0.635	<1.0	PASS
E046991-09	Fountain by A126	11/15/2016	5:57	6.9	0.235	<1.0	PASS
E046991-10	Fountain by B139	11/15/2016	5:58	6.9	0.359	1.3	PASS
E046991-11	Handicap Fountain by B133	11/15/2016	5:59	6.9	0.141	1.4	PASS
E046991-12	Fountain by B132	11/15/2016	5:59	6.9	0.346	1.4	PASS
E046991-13	Bubbler Rm B130	11/15/2016	6:01	6.9	0.289	<1.0	PASS
E046991-14	Bubbler Rm B134	11/15/2016	6:03	6.9	0.306	<1.0	PASS
E046991-15	Bubbler Rm B	11/15/2016	6:04	6.9	0.322	<1.0	PASS
E046991-16	Fountain D111 Right	11/15/2016	6:06	6.9	0.244	<1.0	PASS
E046991-17	Fountain D110 Left	11/15/2016	6:07	6.9	0.313	<1.0	PASS
E046991-18	Fountain E104	11/15/2016	6:08	7.0	0.238	<1.0	PASS
E046991-19	Fountain E103	11/15/2016	6:08	6.9	0.252	<1.0	PASS
E046991-20	Bubbler E101	11/15/2016	6:09	6.9	0.247	<1.0	PASS
E046991-21	Bubbler C124	11/15/2016	6:10	6.9	0.125	<1.0	PASS
E046991-22	Fountain Right C108	11/15/2016	6:11	6.9	0.287	<1.0	PASS
E046991-23	Fountain Left C108	11/15/2016	6:11	7.2	0.193	<1.0	PASS

Runnymede ES

Sandymount ES

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047272-01	Fountain by Rm 506	12/07/2016	05:47	6.8	0.108	<1.0	PASS
E047272-02	Kitchen Hand Sink	12/07/2016	05:48	6.8	0.332	6.4	PASS
E047272-03	Kitchen Triple Sink Right	12/07/2016	05:49	6.9	0.331	7.9	PASS
E047272-04	Kitchen Triple Slnk Left	12/07/2016	05:49	6.9	0.327	7.2	PASS
E047272-05	Kitchen Pot Filler	12/07/2016	05:50	7.0	0.100	5.2	PASS
E047272-06	Dishroom Hand Sink	12/07/2016	05:51	7.1	0.201	3.1	PASS
E047272-07	Fountain Outside Gym (Rm 513)	12/07/2016	05:52	7.1	0.091	<1.0	PASS
E047272-08	Fountain Between 415 & 416	12/07/2016	05:53	7.1	0.068	<1.0	PASS
E047272-09	Fountain by 406	12/07/2016	05:55	7.1	0.101	<1.0	PASS
E047272-10	Fountain Between 112 & 113	12/07/2016	05:56	7.2	0.058	<1.0	PASS
E047272-11	Sink Rm 106	12/07/2016	05:56	7.2	0.295	2.8	PASS
E047272-12	Sink Rm 105 (Health)	12/07/2016	05:57	7.2	0.186	4.6	PASS
E047272-13	Fountain Outside Media Ctr Right	12/07/2016	05:59	7.2	0.118	<1.0	PASS
E047272-14	Fountain Outside Media Ctr Left	12/07/2016	06:00	7.2	0.110	<1.0	PASS
E047272-15	Sink Rm 208	12/07/2016	06:02	7.2	0.233	1.8	PASS
E047272-16	Fountain by Rm 131 Right	12/07/2016	06:02	7.2	0.087	<1.0	PASS
E047272-17	Fountain by Rm 131 Left	12/07/2016	06:02	7.2	0.077	<1.0	PASS

Shiloh Middle

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047107-01	Fountain Entrance Right	11/23/2016	06:35	7.3	0.227	<1.0	PASS
E047107-02	Fountain Entrance Left	11/23/2016	06:35	7.3	0.205	<1.0	PASS
E047107-03	Fountain Cafeteria Right	11/23/2016	06:37	7.4	0.177	<1.0	PASS
E047107-04	Fountain Cafeteria Left	11/23/2016	06:37	7.4	0.227	<1.0	PASS
E047107-05	Dishroom Double Sink Right	11/23/2016	06:40	7.3	0.269	17.7	PASS
E047107-06	Dishroom Double Sink Left	11/23/2016	06:40	7.4	0.351	15.5	PASS
E047107-07	Dishroom Hand Sink	11/23/2016	06:41	7.4	0.202	32.2	FAIL
E047107-08	Kitchen Pot Filler	11/23/2016	06:41	7.4	0.228	5.0	PASS
E047107-09	Kitchen Hand Sink Left	11/23/2016	06:42	7.4	0.172	54.8	FAIL
E047107-10	Kitchen Double Slnk	11/23/2016	06:43	7.4	0.288	6.2	PASS
E047107-11	Kitchen Hand Sink by Serving Line Right	11/23/2016	06:44	7.4	0.437	18.3	PASS
E047107-12	Faculty Lounge Sink	11/23/2016	06:44	7.4	0.156	3.7	PASS
E047107-13	Fountain Outside Rm 213, Right	11/23/2016	06:47	7.4	0.145	<1.0	PASS
E047107-14	Fountain Outside Rm 213, Left	11/23/2016	06:47	7.5	0.172	<1.0	PASS
E047107-15	Fountain Outside Rm 253	11/23/2016	06:48	7.5	0.201	<1.0	PASS
E047107-16	Fountain Outside Rm 280	11/23/2016	06:49	7.5	0.125	<1.0	PASS
E047107-17	Fountain Outside Rm 309	11/23/2016	06:50	7.5	0.128	<1.0	PASS
E047107-18	Fountain Outside Rm 190	11/23/2016	06:51	7.5	0.117	<1.0	PASS
E047107-19	Fountain Outside Rm 153	11/23/2016	06:54	7.5	0.172	<1.0	PASS
E047107-20	Fountain Tech Hall	11/23/2016	07:00	7.5	0.189	<1.0	PASS
E047107-21	Room 505 Sink 1	11/23/2016	07:01	7.5	0.171	<1.0	PASS
E047107-22	Room 505 Sink 2	11/23/2016	07:01	7.5	0.202	1.2	PASS
E047107-23	Room 505 Sink 3	11/23/2016	07:01	7.5	0.191	<1.0	PASS
E047107-24	Room 505 Sink 4	11/23/2016	07:01	7.5	0.235	1.1	PASS
E047107-25	Room 505 Sink 5	11/23/2016	07:02	7.5	0.184	<1.0	PASS
E047107-26	Room 505 Sink 6	11/23/2016	07:02	7.5	0.242	<1.0	PASS
E047107-27	Room 505 Sink 7	11/23/2016	07:02	7.5	0.279	2.6	PASS
E047107-28	Room 505 Teachers Srarion	11/23/2016	07:03	7.4	0.162	4.9	PASS
E047107-29	Office Kitchen Sink	11/23/2016	07:06	7.4	0.182	1.4	PASS

Shiloh Middle

E047107-30	Health Suite Sink	11/23/2016	07:08	7.4	0.275	14.7	PASS
------------	-------------------	------------	-------	-----	-------	------	------

South Carroll HS

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047144-01	Kitchen Rear Triple Sink	11/29/2016	05:50	6.5	0.650	20.6	FAIL
E047144-02	Kitchen Prep Sink	11/29/2016	05:52	6.4	0.506	11.3	PASS
E047144-03	Kitchen Hand Sink Front	11/29/2016	05:53	6.4	0.563	7.3	PASS
E047144-04	Kitchen Hand Sink Rear	11/29/2016	05:55	6.4	0.518	7.0	PASS
E047144-05	Kitchen Restroom Hand Sink	11/29/2016	05:57	6.4	0.599	13.8	PASS
E047144-06	Fountain Cafeteria Hall Right	11/29/2016	06:00	6.4	0.845	<1.0	PASS
E047144-07	Fountain Cafeteria Hall Left	11/29/2016	06:02	6.4	0.688	<1.0	PASS
E047144-08	Fountain F-130 Right	11/29/2016	06:06	6.4	0.722	<1.0	PASS
E047144-09	Fountain F-130 Left	11/29/2016	06:07	6.4	0.700	<1.0	PASS
E047144-10	Fountain B-38 Left	11/29/2016	06:08	6.4	0.643	<1.0	PASS
E047144-11	Fountain B-38 Right	11/29/2016	06:09	6.4	0.622	<1.0	PASS
E047144-12	Fountain H-182 Left	11/29/2016	06:10	6.4	0.992	1.3	PASS
E047144-13	Fountain H-182 Right	11/29/2016	06:11	6.3	1.04	1.7	PASS
E047144-14	Music Room Bubbler	11/29/2016	06:14	6.3	0.831	4.8	PASS
E047144-15	H Lobby Fountain Right	11/29/2016	06:17	6.2	1.48	3.3	FAIL
E047144-16	H Lobby Fountain Left	11/29/2016	06:18	6.2	1.47	3.3	FAIL
E047144-17	Main Lobby Fountain Left	11/29/2016	06:21	6.2	0.538	1.1	PASS
E047144-18	Main Lobby Fountain Right	11/29/2016	06:20	6.2	0.601	<1.0	PASS
E047144-19	Main Office Fountain Right	11/29/2016	06:23	6.1	1.82	5.7	FAIL
E047144-20	Main Office Fountain Left	11/29/2016	06:23	6.1	1.80	3.5	FAIL
E047144-21	Fountain D-109 Right	11/29/2016	06:29	6.1	1.09	<1.0	PASS
E047144-22	Fountain D-109 Left	11/29/2016	06:30	6.1	1.15	<1.0	PASS
E047144-23	Fountain D Wing Right	11/29/2016	06:33	6.1	0.772	10.7	PASS
E047144-24	Fountain D Wing Left	11/29/2016	06:34	6.2	0.313	1.5	PASS
E047144-25	Fountain F Wing Right	11/29/2016	06:35	6.2	0.320	2.1	PASS
E047144-26	Fountain F Wing Left	11/29/2016	06:36	6.2	0.583	2.1	PASS
E047144-27	G Wing Fountain Boy's RR	11/29/2016	06:38	6.3	0.330	4.5	PASS
E047144-28	G Wing Fountain Girl's RR	11/29/2016	06:40	6.3	0.290	<1.0	PASS

South Carroll HS

E047144-29	Vo-Tech Lobby Fountain Right	11/29/2016	06:42	6.3	0.432	6.7	PASS
E047144-30	Vo-Tech Lobby Fountain Left	11/29/2016	06:44	6.4	0.251	1.2	PASS
E047144-31	Vo-Tech V-320 Fountain	11/29/2016	06:45	6.4	0.712	11.0	PASS
E047144-32	Vo-Tech V-314 Fountain	11/29/2016	06:47	6.4	0.468	8.7	PASS
E047144-33	Fountain Outdoor Sciene Rm	11/29/2016	06:53	6.3	3.07	6.2	FAIL
E047144-34	Fountain Boy's Locker Rm	11/29/2016	07:00	6.3	1.84	1.1	FAIL
E047144-35	Fountain Girl's Locker Rm	11/29/2016	07:02	6.3	1.62	2.2	FAIL

Spring Garden ES

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047106-01	Fountain at Entrance	11/23/2016	06:05	7.1	0.097	<1.0	PASS
E047106-02	Bubbler Rm 101	11/23/2016	06:06	7.1	0.174	4.6	PASS
E047106-03	Bubbler Rm 102	11/23/2016	06:07	7.1	0.294	18.3	PASS
E047106-04	Bubbler Rm 103	11/23/2016	06:07	7.1	0.408	13.8	PASS
E047106-05	Kitchen Hand Sink	11/23/2016	06:09	7.1	0.429	32.6	FAIL
E047106-06	Kitchen Single Slnk	11/23/2016	06:09	7.2	0.310	5.8	PASS
E047106-07	Kitchen Pot Filler	11/23/2016	06:10	7.1	0.082	6.6	PASS
E047106-08	Fountain Cafeteria	11/23/2016	06:11	7.3	0.218	<1.0	PASS
E047106-09	Fountain 4th-5th Grade Hallway	11/23/2016	06:12	7.2	0.100	<1.0	PASS
E047106-10	Fountain Gym	11/23/2016	06:12	7.3	0.228	<1.0	PASS
E047106-11	Fountain 3rd Grade Hallway	11/23/2016	06:13	7.2	0.355	1.0	PASS
E047106-12	Fountain 2nd Grade Hallway	11/23/2016	06:15	7.3	0.205	<1.0	PASS
E047106-13	Bubbler Annex 1	11/23/2016	06:16	7.3	0.199	1.1	PASS
E047106-14	Bubbler Annex 2	11/23/2016	06:16	7.3	0.159	<1.0	PASS
E047106-15	Bubbler Annex 3	11/23/2016	06:17	7.3	0.165	1.8	PASS
E047106-16	Teachers Lounge Slnk	11/23/2016	06:19	7.3	0.315	2.9	PASS

Sykesville Middle

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047182-01	Fountain Outside of Gym (By Rm 124)	12/01/2016	05:29	8.1	0.162	3.1	PASS
E047182-02	Fountain by Rm 152	12/01/2016	05:30	8.2	0.071	1.0	PASS
E047182-03	Fountain by Rm 164 Right	12/01/2016	05:32	8.2	0.063	<1.0	PASS
E047182-04	Fountain by Rm 164 Left	12/01/2016	05:32	8.2	0.049	<1.0	PASS
E047182-05	Fountain by Rm 175 Right	12/01/2016	05:34	8.2	0.095	<1.0	PASS
E047182-06	Fountain by Rm 175 Left	12/01/2016	05:34	8.2	0.059	<1.0	PASS
E047182-07	Fountain by Media Ctr Right	12/01/2016	05:37	8.2	0.107	<1.0	PASS
E047182-08	Fountain by Media Ctr Left	12/01/2016	05:37	8.3	0.094	<1.0	PASS
E047182-09	Fountain by Rm 211 Right	12/01/2016	05:39	8.3	0.073	<1.0	PASS
E047182-10	Fountain by Rm 211 Left	12/01/2016	05:39	8.3	0.082	<1.0	PASS
E047182-11	Fountain by Rm 203 Right	12/01/2016	05:41	8.3	0.080	<1.0	PASS
E047182-12	Fountain by Rm 203 Left	12/01/2016	05:41	8.3	0.046	<1.0	PASS
E047182-13	Fountain by Main Office	12/01/2016	05:45	8.2	0.120	2.7	PASS
E047182-14	Sink Rm 103	12/01/2016	05:45	8.2	0.065	7.1	PASS
E047182-15	Fountain by Gym Door Red Hallway	12/01/2016	05:47	8.3	0.075	<1.0	PASS
E047182-16	Sink Rm 152 Station 4	12/01/2016	05:50	8.2	0.099	5.6	PASS
E047182-17	Sink Rm 152 Station 3	12/01/2016	05:50	8.0	0.101	7.3	PASS
E047182-18	Sink Rm 152 Station 2	12/01/2016	05:50	8.0	0.083	10.2	PASS
E047182-19	Sink Rm 152 Station 1	12/01/2016	05:50	8.0	0.098	4.0	PASS
E047182-20	Sink Rm 152 Station 5	12/01/2016	05:51	8.0	0.123	8.0	PASS
E047182-21	Fountain Rm 025	12/01/2016	05:52	8.1	0.088	2.1	PASS
E047182-22	Fountain by Rm 035	12/01/2016	05:53	8.1	0.078	2.2	PASS
E047182-23	Fountain Rm 021	12/01/2016	05:54	8.1	0.115	<1.0	PASS
E047182-24	Fountain Cafeteria	12/01/2016	05:55	8.2	0.097	7.3	PASS
E047182-25	Dishroom Hand Sink	12/01/2016	05:55	7.8	0.085	5.4	PASS
E047182-26	Dishroom Triple Slnk Right	12/01/2016	05:56	7.2	0.085	69.5	FAIL
E047182-27	Dishroom Triple Slnk Left	12/01/2016	05:56	7.0	0.208	182	FAIL
E047182-28	Kitchen Pot Filler	12/01/2016	05:57	7.9	0.048	6.9	PASS
E047182-29	Kitchen Island Sink	12/01/2016	05:57	7.8	0.104	7.2	PASS
E047182-30	Kitchen Hand Sink	12/01/2016	05:58	7.7	0.072	3.0	PASS

Sykesville Middle

E047182-31	Kitchen Double Sink	12/01/2016	05:58	7.7	0.084	40.8	FAIL
------------	---------------------	------------	-------	-----	-------	------	------

Taneytown ES

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E046992-01	Fountain Kindergarten	11/15/2016	06:31	7.3	0.619	<1.0	PASS
E046992-02	Fountain Cafeteria	11/15/2016	06:32	7.3	0.163	<1.0	PASS
E046992-03	Kitchen Hand Sink Office	11/15/2016	06:32	7.3	0.331	7.8	PASS
E046992-04	Kitchen Hand Sink Back	11/15/2016	06:32	7.3	0.374	5.3	PASS
E046992-05	Kitchen Triple Sink	11/15/2016	06:33	7.4	0.401	26.9	FAIL
E046992-06	Dishwashing Room Hand Sink	11/15/2016	06:33	7.4	0.856	26.4	FAIL
E046992-07	Dishwashing Room Sprayer	11/15/2016	06:33	7.4	0.622	6.0	PASS
E046992-08	Dishwashing Room Triple Sink	11/15/2016	06:34	7.4	0.193	76.2	FAIL
E046992-09	Pre-K Gym Fountain Right	11/15/2016	06:36	7.4	0.306	<1.0	PASS
E046992-10	Pre-K Gym Fountain Left	11/15/2016	06:36	7.4	0.270	<1.0	PASS
E046992-11	2nd Grade Fountain	11/15/2016	06:38	7.4	0.560	<1.0	PASS
E046992-12	4th Grade Fountain	11/15/2016	06:39	7.4	0.408	<1.0	PASS
E046992-13	3rd Grade Fountain	11/15/2016	06:41	7.4	0.359	<1.0	PASS
E046992-14	5th Grade Fountain	11/15/2016	06:43	7.4	0.429	<1.0	PASS

West Middle

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047247-01	Fountain by Rm 6 Right	12/06/2016	06:43	6.7	0.286	<1.0	PASS
E047247-02	Fountain by Rm 6 Left	12/06/2016	06:43	6.8	0.305	1.1	PASS
E047247-03	Kitchen Double Sink	12/06/2016	06:47	6.8	0.155	2.0	PASS
E047247-04	Kitchen Triple Sink Right	12/06/2016	06:48	6.9	0.324	1.1	PASS
E047247-05	Kitchen Triple Sink Left	12/06/2016	06:48	6.9	0.242	2.5	PASS
E047247-06	Cafeteria Fountain by Kitchen	12/06/2016	06:49	6.9	0.546	3.0	PASS
E047247-07	Cafeteria Fountain by Entrance	12/06/2016	06:50	6.9	0.512	1.7	PASS
E047247-08	Fountain by Rm 47 Right	12/06/2016	06:52	7.0	0.285	1.9	PASS
E047247-09	Fountain by Rm 47 Left	12/06/2016	06:52	7.0	0.163	<1.0	PASS
E047247-10	Fountain by Rm 49B	12/06/2016	06:53	7.0	0.662	<1.0	PASS
E047247-11	Media Center Office Sink	12/06/2016	06:55	7.0	0.794	2.3	PASS
E047247-12	Fountain by Rm 47 Right	12/06/2016	06:57	7.1	0.316	2.6	PASS
E047247-13	Fountain by Rm 47 Left	12/06/2016	06:57	7.1	0.207	<1.0	PASS
E047247-14	Instrumental Rm Office Sink	12/06/2016	06:58	7.1	0.515	7.5	PASS
E047247-15	Fountain Outside Cafeteria Right	12/06/2016	07:00	7.1	0.298	<1.0	PASS
E047247-16	Fountain Outside Cafeteria Left	12/06/2016	07:00	7.1	0.334	<1.0	PASS
E047247-17	Fountain Girl's Locker Rm	12/06/2016	07:01	7.1	0.462	<1.0	PASS
E047247-18	Sink Girl's Phys Ed Office	12/06/2016	07:02	7.1	0.379	16.9	PASS
E047247-19	Fountain Boy's Gym	12/06/2016	07:04	7.2	0.157	<1.0	PASS
E047247-20	Boy's Gym Office Sink	12/06/2016	07:04	7.2	0.342	10.4	PASS
E047247-21	Sink Rm 38	12/06/2016	07:07	7.2	0.432	1.6	PASS
E047247-22	Sink Rm 37 Station 1	12/06/2016	07:08	7.2	0.270	11.6	PASS
E047247-23	Sink Rm 37 Station 2	12/06/2016	07:09	7.2	0.267	11.1	PASS
E047247-24	Sink Rm 37 Station 3	12/06/2016	07:10	7.2	0.244	11.8	PASS
E047247-25	Sink Rm 37 Station 4	12/06/2016	07:10	7.2	0.198	3.8	PASS
E047247-26	Sink Rm 37 Station 5	12/06/2016	07:10	7.2	0.171	6.9	PASS
E047247-27	Sink Rm 37 Station 6	12/06/2016	07:10	7.2	0.196	3.6	PASS
E047247-28	Sink Rm 37 Station 7	12/06/2016	07:10	7.1	0.178	13.2	PASS

West Middle

E047247-29	Fountain Outside Main Office	12/06/2016	07:12	7.1	0.650	<1.0	PASS
E047247-30	Fountain by Rm 14 Right	12/06/2016	07:15	7.2	0.387	1.1	PASS
E047247-31	Fountain by Rm 14 Left	12/06/2016	07:15	7.2	0.303	<1.0	PASS
E047247-32	Fountain by Rm 32 Right	12/06/2016	07:17	7.2	0.341	<1.0	PASS
E047247-33	Fountain by Rm 32 Left	12/06/2016	07:17	7.3	0.176	<1.0	PASS
E047247-34	Fountain by Rm 23 Right	12/06/2016	07:20	7.3	0.347	1.1	PASS
E047247-35	Fountain by Rm 23 Left	12/06/2016	06:13	7.3	0.335	1.2	PASS
E047247-36	Fountain Portable 62	12/06/2016	06:13	7.3	0.716	<1.0	PASS

Westminster ES

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047018-01	Cafeteria Fountain	11/16/2016	07:20	7.0	0.681	<1.0	PASS
E047018-02	Fountain Back Lobby Right	11/16/2016	07:24	6.5	2.25	<1.0	FAIL
E047018-03	Fountain Bak Lobby Left	11/16/2016	07:34	6.5	1.98	<1.0	FAIL
E047018-04	Room 408 Bubblers	11/16/2016	07:25	6.7	0.399	2.2	PASS
E047018-05	Room 304 Bubblers	11/16/2016	07:27	6.8	2.27	1.1	FAIL
E047018-06	Room 303 Bubblers	11/16/2016	07:28	6.8	2.42	1.2	FAIL
E047018-07	Room 301 Bubblers	11/16/2016	07:29	6.9	1.55	2.3	FAIL
E047018-08	Room 302 Bubblers	11/16/2016	07:30	6.9	1.98	2.3	FAIL
E047018-09	Room 305 Bubblers	11/16/2016	07:31	6.9	1.17	3.3	PASS
E047018-10	Room 310 Bubblers	11/16/2016	07:32	7.0	2.47	<1.0	FAIL
E047018-11	Room 309 Bubblers	11/16/2016	07:33	7.0	2.84	<1.0	FAIL
E047018-12	Room 308 Bubblers	11/16/2016	07:33	7.0	2.45	<1.0	FAIL
E047018-13	Room 307 Bubblers	11/16/2016	07:33	7.0	2.58	<1.0	FAIL
E047018-14	Fountain Court Yard	11/16/2016	07:35	7.1	0.320	<1.0	PASS
E047018-15	Fountain 1st Grade Hall	11/16/2016	07:36	7.1	0.312	<1.0	PASS
E047018-16	Fountain Main Lobby	11/16/2016	07:37	7.1	1.69	1.4	FAIL
E047018-17	Kitchen Hand Sink	11/16/2016	07:38	7.1	1.07	10.0	PASS
E047018-18	Triple Sink Right	11/16/2016	07:41	7.1	0.781	21.1	FAIL
E047018-19	Triple Sink Left	11/16/2016	07:41	7.1	0.823	45.4	FAIL
E047018-20	Hand Sink by Triple Sink	11/16/2016	07:42	7.1	0.753	19.7	PASS
E047018-21	Room 101 Bubblers	11/16/2016	07:46	7.0	2.46	<1.0	FAIL
E047018-22	Room 102 Bubblers	11/16/2016	07:47	7.1	2.39	<1.0	FAIL
E047018-23	Room 103 Bubblers	11/16/2016	07:48	7.1	2.74	<1.0	FAIL
E047018-24	Room 104 Bubblers	11/16/2016	07:49	7.1	1.86	<1.0	FAIL
E047018-25	Room 105 Bubblers	11/16/2016	07:51	7.1	1.71	7.0	FAIL
E047018-26	Room 106 Bubblers	11/16/2016	07:51	7.1	2.23	6.2	FAIL
E047018-27	Room 107 Bubblers	11/16/2016	07:53	7.1	2.86	<1.0	FAIL
E047018-28	Room 108 Bubblers	11/16/2016	07:53	7.1	2.57	<1.0	FAIL
E047018-29	Room 109 Bubblers	11/16/2016	07:54	7.1	2.60	<1.0	FAIL
E047018-30	Room 110 Bubblers	11/16/2016	07:54	7.1	2.93	<1.0	FAIL
E047018-31	Room 201 Bubblers	11/16/2016	07:56	7.1	2.53	1.1	FAIL
E047018-32	Room 202 Bubblers	11/16/2016	07:56	7.1	2.35	1.1	FAIL

Westminster ES

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047018-33	Room 203 Bubblers	11/16/2016	07:57	7.1	2.41	<1.0	FAIL
E047018-34	Room 204 Bubblers	11/16/2016	07:57	7.2	1.59	<1.0	FAIL
E047018-35	Room 209 Bubblers	11/16/2016	07:59	7.3	0.898	<1.0	PASS
E047018-36	Room 210 Bubblers	11/16/2016	07:59	7.3	0.857	<1.0	PASS
E047018-37	Room 211 Bubblers	11/16/2016	08:00	7.2	1.95	<1.0	FAIL
E047018-38	Room 212 Bubblers	11/16/2016	08:00	7.2	2.07	<1.0	FAIL
E047018-39	Room 213 Bubblers	11/16/2016	08:00	7.2	2.52	<1.0	FAIL
E047018-40	Teachers Lounge Bubblers	11/16/2016	08:04	7.2	2.05	2.6	FAIL

Westminster HS

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047040-01	Kitchen Ground Floor by Ice Machine	11/17/2016	05:55	7.8	0.108	4.9	PASS
E047040-02	Kitchen Ground Floor by Steamers	11/17/2016	05:57	7.8	0.091	4.6	PASS
E047040-03	Kitchen Ground Floor Porcelain Sink	11/17/2016	05:59	7.7	0.092	11.8	PASS
E047040-04	Kitchen Ground Floor by Fire Blanket	11/17/2016	06:00	7.6	0.119	7.4	PASS
E047040-05	Loading Dock Fountain	11/17/2016	06:02	7.6	0.078	<1.0	PASS
E047040-06	A1 Fountain	11/17/2016	06:05	7.7	0.061	<1.0	PASS
E047040-07	A8 Fountain	11/17/2016	06:07	7.7	0.068	<1.0	PASS
E047040-08	Locker Hall Fountain	11/17/2016	06:10	7.7	0.072	<1.0	PASS
E047040-09	Men's Shower Fountain	11/17/2016	06:11	7.7	0.085	<1.0	PASS
E047040-10	Men's Locker Rm Fountain	11/17/2016	06:11	7.7	0.061	<1.0	PASS
E047040-11	Women's Shower Fountain	11/17/2016	06:14	7.7	0.077	<1.0	PASS
E047040-12	Women.s Locker Rm Fountain	11/17/2016	06:13	7.7	0.086	<1.0	PASS
E047040-13	Fountain E-303	11/17/2016	06:15	7.7	0.081	1.2	PASS
E047040-14	Fountain Shop Room	11/17/2016	06:16	7.7	0.203	22.7	FAIL
E047040-15	Fountain Ag Shop	11/17/2016	06:18	7.6	0.044	4.4	PASS
E047040-16	Fountain E141	11/17/2016	06:21	7.7	0.040	<1.0	PASS
E047040-17	Home Ec Sink E125	11/17/2016	06:25	7.7	0.041	<1.0	PASS
E047040-18	Gym Lobby #1 Fountain	11/17/2016	06:28	7.7	0.042	<1.0	PASS
E047040-19	Gym Lobby #2 Fountain	11/17/2016	06:28	7.7	0.042	<1.0	PASS
E047040-20	Fountain A114	11/17/2016	06:30	7.7	0.037	<1.0	PASS
E047040-21	Fountain A116	11/17/2016	06:32	7.7	0.064	<1.0	PASS
E047040-22	Fountain A128	11/17/2016	06:35	7.7	0.046	<1.0	PASS
E047040-23	Fountain A105	11/17/2016	06:37	7.7	0.091	<1.0	PASS
E047040-24	Kitchen 2nd Floor Serving Sink	11/17/2016	06:39	7.5	0.113	12.3	PASS
E047040-25	Kitchen 2nd Floor Dishroom	11/17/2016	06:40	7.5	0.086	7.7	PASS
E047040-26	Kitchen 2nd Floor Boys Side	11/17/2016	06:41	7.4	0.153	39.1	FAIL

Westminster HS

E047040-27	2nd Floor Cafeteria Fountain #1	11/17/2016	06:43	7.5	0.055	<1.0	PASS
E047040-28	2nd Floor Cafeteria Fountain #2	11/17/2016	06:43	7.5	0.075	1.2	PASS
E047040-29	Fountain A205	11/17/2016	06:45	7.5	0.124	<1.0	PASS
E047040-30	Fountain A230	11/17/2016	06:47	7.5	0.040	<1.0	PASS
E047040-31	Fountain A227	11/17/2016	06:49	7.6	0.108	<1.0	PASS
E047040-32	Fountain A218	11/17/2016	06:50	7.6	0.090	<1.0	PASS
E047040-33	C Section 2nd Floor	11/17/2016	06:55	7.6	0.052	4.4	PASS
E047040-34	3rd Floor Kitchen Boy's Side	11/17/2016	06:57	7.6	0.070	6.7	PASS
E047040-35	3rd Floor Kitchen Wash Sink	11/17/2016	06:58	7.5	0.077	20.3	FAIL
E047040-36	3rd Floor Kitchen Dish Room	11/17/2016	07:00	7.5	0.078	28.4	FAIL
E047040-37	3rd Floor Cafeteria Fountain	11/17/2016	07:03	7.4	0.084	5.7	PASS
E047040-38	3rd Floor Cafeteria	11/17/2016	07:02	7.5	0.068	<1.0	PASS
E047040-39	Fountain A311	11/17/2016	07:06	7.5	0.057	<1.0	PASS
E047040-40	Fountain A306	11/17/2016	07:08	7.5	0.045	<1.0	PASS
E047040-41	Fountain PC07	11/17/2016	07:15	7.5	0.309	1.9	PASS
E047040-42	Fountain "A" PC0	11/17/2016	07:16	7.6	0.753	3.0	PASS

William Winchester ES

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047248-01	Fountain Cafeteria Entrance	12/06/2016	07:28	7.3	0.427	1.9	PASS
E047248-02	Fountain Cafeteria by Kitchen	12/06/2016	07:28	7.4	0.404	1.6	PASS
E047248-03	Kitchen Hand Slnk (back)	12/06/2016	07:29	7.4	0.243	18.5	PASS
E047248-04	Kitchen Triple Sink Right	12/06/2016	07:30	7.3	0.140	11.5	PASS
E047248-05	Kitchen Triple Sink Left	12/06/2016	07:30	7.3	0.491	5.0	PASS
E047248-06	Kitchen Double Sink	12/06/2016	07:31	7.3	0.174	6.9	PASS
E047248-07	Teachers Lounge Sink	12/06/2016	07:32	7.3	0.211	4.8	PASS
E047248-08	Nurse's Office Sink	12/06/2016	07:32	7.3	0.356	7.4	PASS
E047248-09	Media Center Office Sink	12/06/2016	07:34	7.2	0.338	26.0	FAIL
E047248-10	Fountain Upper Level by Rm 13B Right	12/06/2016	07:36	7.3	0.138	1.3	PASS
E047248-11	Fountain Upper Level by Rm 13B Left	12/06/2016	07:36	7.3	0.091	1.6	PASS
E047248-12	Fountain by Rm 12 Right	12/06/2016	07:37	7.3	0.137	1.3	PASS
E047248-13	Fountain by Tm 12 Left	12/06/2016	07:37	7.3	0.107	1.5	PASS
E047248-14	Fountain Outside Gym Right	12/06/2016	07:39	7.3	0.183	1.0	PASS
E047248-15	Fountain Outside Gyne Left	12/06/2016	07:39	7.3	0.212	1.2	PASS
E047248-16	K4 Bubbler	12/06/2016	07:40	7.3	0.670	1.2	PASS
E047248-17	K3 Bubbler	12/06/2016	07:40	7.4	0.487	<1.0	PASS
E047248-18	K2 Bubbler	12/06/2016	07:41	7.3	0.650	1.4	PASS
E047248-19	K1 Bubbler	12/06/2016	07:42	7.3	0.628	1.5	PASS
E047248-20	K0 Bubbler	12/06/2016	07:43	7.3	0.656	1.5	PASS
E047248-21	Portable 1130 Fountain	12/06/2016	07:45	7.3	0.534	3.9	PASS
E047248-22	Portable 1129 Fountain	12/06/2016	07:47	7.3	0.456	<1.0	PASS
E047248-23	Portable 1127 Kitchen	12/06/2016	07:48	7.3	0.644	1.4	PASS

Winfield ES

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047147-01	Kitchen Sink	11/29/2016	07:26	7.5	0.160	14.9	PASS
E047147-02	Kitchen Pot Filler	11/29/2016	07:27	7.6	0.147	<1.0	PASS
E047147-03	Kitchen Hand Sink	11/29/2016	07:28	7.6	0.137	7.7	PASS
E047147-04	Room 025 Bubblers	11/29/2016	07:28	7.6	0.111	1.1	PASS
E047147-05	Room 023 Bubblers	11/29/2016	07:29	7.6	0.083	<1.0	PASS
E047147-06	Room 034 Bubblers	11/29/2016	07:30	7.6	0.084	<1.0	PASS
E047147-07	Fountain by Room 072	11/29/2016	07:31	7.6	0.039	<1.0	PASS
E047147-08	Main Lobby Fountain	11/29/2016	07:32	7.6	0.167	<1.0	PASS
E047147-09	Staff Lounge Sink	11/29/2016	07:33	7.6	0.102	<1.0	PASS
E047147-10	Health Room Sink	11/29/2016	07:34	7.6	0.111	3.9	PASS
E047147-11	Fountain Outside Gym	11/29/2016	07:36	7.6	0.074	<1.0	PASS
E047147-12	Fountain by Room 049	11/29/2016	07:37	7.6	0.083	<1.0	PASS
E047147-13	Fountain by Room 154	11/29/2016	07:38	7.6	0.041	<1.0	PASS
E047147-14	Fountain by Room 134	11/29/2016	07:39	7.6	0.094	<1.0	PASS
E047147-15	Room 139 Bubblers	11/29/2016	07:41	7.6	0.196	<1.0	PASS
E047147-16	Room 138 Bubblers	11/29/2016	07:42	7.6	0.110	1.2	PASS
E047147-17	Fountain by Room 125	11/29/2016	07:42	7.6	0.108	<1.0	PASS
E047147-18	Fountain by Room 115	11/29/2016	07:43	7.6	0.149	<1.0	PASS
E047147-19	Room 115 Sink Teachers Lounge	11/29/2016	07:44	7.6	0.070	<1.0	PASS

Winters Mill HS

Lab Identification	Sample Identification	Date Sampled	Time Sampled	pH (Range 6.5-8.5)	Copper mg/L (< 1.3 mg/L)	Lead ppb (< 20ppb)	Pass/Fail Copper/Lead
E047195-01	Kitchen Hand Sink Behind Serving Line	12/02/2016	05:58	6.4	0.305	2.4	PASS
E047195-02	Kitchen Pot Filler Right	12/02/2016	05:59	6.6	1.03	5.9	PASS
E047195-03	Kitchen Pot Filler Center	12/02/2016	05:59	6.7	0.239	1.5	PASS
E047195-04	Kitchen Pot Filler Left	12/02/2016	05:59	6.8	0.183	2.2	PASS
E047195-05	Kitchen Hand Sink Outside Lockers	12/02/2016	06:00	6.9	0.333	11.0	PASS
E047195-06	Kitchen Double Sink by D122	12/02/2016	06:01	6.9	0.209	6.5	PASS
E047195-07	Dishroom Triple Sink Right	12/02/2016	06:02	6.9	0.236	1.3	PASS
E047195-08	Dishroom Triple Sink Left	12/02/2016	06:02	7.0	0.388	4.1	PASS
E047195-09	Dishroom Hand Sink	12/02/2016	06:02	7.0	0.296	8.5	PASS
E047195-10	Faculty Lounge Sink D113	12/02/2016	06:05	7.1	0.136	<1.0	PASS
E047195-11	Fountain Outside Cafeteria Right	12/02/2016	06:06	7.1	0.375	<1.0	PASS
E047195-12	Fountain Outside Cafeteria Center	12/02/2016	06:06	7.1	0.173	<1.0	PASS
E047195-13	Fountain Outside Cafeteria Left	12/02/2016	06:07	7.2	0.351	<1.0	PASS
E047195-14	Fountain Boy's Locker Rm E105	12/02/2016	06:09	7.2	0.351	<1.0	PASS
E047195-15	Fountain Boy's Locker Rm E106	12/02/2016	06:09	7.2	0.283	<1.0	PASS
E047195-16	Coaches Office Sink E153	12/02/2016	06:11	7.2	0.323	2.9	PASS
E047195-17	Fountain Girls's Locker Rm E107	12/02/2016	06:13	7.3	0.533	<1.0	PASS
E047195-18	Fountain Girl's Locker Rm E108	12/02/2016	06:14	7.3	0.523	<1.0	PASS
E047195-19	Sink Training Rm E131	12/02/2016	06:15	7.3	0.249	2.2	PASS
E047195-20	Fountain by E133	12/02/2016	06:15	7.3	0.121	<1.0	PASS
E047195-21	Indoor Concession Stand SInk	12/02/2016	06:17	7.3	0.301	1.1	PASS
E047195-22	Music Rm Sink F107	12/02/2016	06:18	7.4	0.557	<1.0	PASS
E047195-23	Main Office Work Rm Sink C110	12/02/2016	06:21	7.4	0.378	1.1	PASS

Winters Mill HS

E047195-24	Health Service Sink Rm C142	12/02/2016	06:22	7.4	0.397	2.2	PASS
E047195-25	Fountain by Rm C117 Right	12/02/2016	06:23	7.4	0.817	<1.0	PASS
E047195-26	Fountain by Rm C117 Left	12/02/2016	06:23	7.4	0.764	<1.0	PASS
E047195-27	Fountain by Guidance Office Right	12/02/2016	06:24	7.4	0.615	<1.0	PASS
E047195-28	B First Floor Fountain Right	12/02/2016	06:26	7.5	0.485	<1.0	PASS
E047195-29	B First Floor Fountain Left	12/02/2016	06:26	7.4	0.403	<1.0	PASS
E047195-30	Sink Rm A131	12/02/2016	06:27	7.5	0.562	1.9	PASS
E047195-31	A First Floor Fountain Right	12/02/2016	06:28	7.5	0.376	<1.0	PASS
E047195-32	A First Floor Fountain Left	12/02/2016	06:28	7.5	0.436	<1.0	PASS
E047195-33	Sink Rm A123	12/02/2016	06:30	7.5	0.320	<1.0	PASS
E047195-34	Sink Rm B109	12/02/2016	06:32	7.5	0.363	<1.0	PASS
E047195-35	B 2nd Floor Fountain Right	12/02/2016	06:38	7.6	0.452	<1.0	PASS
E047195-36	B 2nd Floor Fountain Left	12/02/2016	06:38	7.6	0.382	<1.0	PASS
E047195-37	B215 Food Lab Sink 1	12/02/2016	06:41	7.5	0.315	1.1	PASS
E047195-38	B215 Food Lab Sink 2	12/02/2016	06:41	7.6	0.356	1.4	PASS
E047195-39	B215 Food Lab Sink 3	12/02/2016	06:41	7.6	0.374	1.1	PASS
E047195-40	B215 Food Lab Sink 4	12/02/2016	06:42	7.6	0.141	<1.0	PASS
E047195-41	B215 Food Lab Sink 5	12/02/2016	06:42	7.6	0.433	<1.0	PASS
E047195-42	B215 Food Lab Sink 6	12/02/2016	06:43	7.6	0.370	<1.0	PASS
E047195-43	B215 Food Lab Sink 7	12/02/2016	06:43	7.6	0.520	5.9	PASS
E047195-44	A 2nd Floor Fountain Right	12/02/2016	06:46	7.6	0.333	<1.0	PASS
E047195-45	A 2nd Floor Fountain Left	12/02/2016	06:46	7.6	0.475	<1.0	PASS